Bulletin 25
Pt.1.

### DEPARTMENT OF THE INTERIOR BUREAU OF MINES

8. Moret, Princen

JOSEPH A. HOLMES, DIRECTOR

### MINING CONDITIONS

UNDER THE

CITY OF SCRANTON, PA.

### REPORT AND MAPS

BY

TN

WILLIAM GRIFFITH AND ELI T. CONNER

WITH A PREFACE BY JOSEPH A. HOLMES AND A CHAPTER BY N. H. DARTON

ENGINEERHIG


23

44

ENGIN STORAGE



WASHINGTON
GOVERNMENT PRINTING OFFICE
1912



### DEPARTMENT OF THE INTERIOR BUREAU OF MINES

JOSEPH A. HOLMES, DIRECTOR

### MINING CONDITIONS

UNDER THE

### CITY OF SCRANTON, PA.

### REPORT AND MAPS

BY

WILLIAM GRIFFITH AND ELI T. CONNER

WITH A PREFACE BY JOSEPH A. HOLMES AND A CHAPTER BY N. H. DARTON



14321

WASHINGTON GOVERNMENT PRINTING OFFICE

Digitized by the Internet Archive in 2011 with funding from University of Toronto

### CONTENTS.

	Page.
Preface	5
Letter of transmittal	7
Summary	9
The reason why	12
Geology	14
History	15
Early developments	15
Mining methods	16
Statistics of coal production	17
Present mining conditions under Scranton	18
Pine Brook colliery	19
Mount Pleasant colliery	21
Capouse colliery	22
West Ridge colliery	23
Richmond No. 3 colliery	24
National colliery	25
Dodge colliery	26
Hampton colliery	26
Bellevue colliery	27
Central colliery	. 28
Hyde Park colliery and Continental colliery	29
Diamond colliery	30
Prichip colliery	
Brisbin colliery	31
Cayuga colliery and Storrs colliery.	32
Oxford colliery	33
Von Storch colliery	35
Leggetts Creek colliery	36
Marvine colliery	37
Dickson colliery	38
Manville colliery	39
Pennsylvania colliery	40
Green Ridge colliery	41
North End colliery.	42
Clearview colliery	43
Bull's Head colliery	43
Mountain Lake colliery	43
Observations on present mining conditions under Scranton	44
Introductory statement.	44
Surface beds.	44
West side of Lackawanna River.	44
Central part of Scranton.	45
Middle beds, Hyde Park and Providence sections	49
Dunmore beds	50
Recapitulation	50
Methods for surface support	51
Natural or pillar support	51

Methods for surface support—Continued.	Page.
Artificial support	51
Flushing	51
Cogs	52
Gob piers	52
Gob stowage in rooms	52
Concrete and masonry piers	53
Iron props.	53
Tests of roof-supporting devices	54
Compressive strength of anthracite	54
Tests at Lehigh University	
Dry filling	
Improved methods of gob stowage	56
Blasting roof and floor in thinner beds.	
Gob piers and timber cogs	
Concrete piers.	
Dry filling with broken stone or sand	58
Suggestions for improvement in mining methods and pillar support	60
Flushing.	60
Culm from old and from fresh-mined banks.	61
Surplus mine rock	61
River sand	62
City refuse	62
Sand from distant points.	63
Plans, specifications, and costs.	63
General conclusions.	69
Notes on sand for mine flushing in the Scranton region, by N. H. Darton	72
Introductory statement.	72
Rock for crushing.	72
Glacial till.	73
Alluvium	75
River sand.	75
Appendix	77
Compressive strength of anthracite coal.	77
Northern coal field.	
Eastern Middle field	
Compressive strength of materials for roof support	
Tests at Lehigh University	83

### ILLUSTRATIONS.

PLATE	1.	Mine workings under a part of the central section of the city of Scranton.	In case
	2.	Mine workings under a part of the central section of the city of Scranton.	Do.
	3.	Mine workings under a part of the central section of the city of Scranton.	Do.
	4.	Mine workings under a part of the east section of the city of Scranton	Do.
	5.	Mine workings under a part of the Green Ridge section of the city of Scranton.	Do.
	6.	Mine workings under a part of the Green Ridge section of the city of Scranton.	Do.
	7.	Mine workings under a part of the Providence section of the city of Scranton.	Do.
	8.	Mine workings under a part of the Providence section of the city of Scranton.	
	9.	Mine workings under a part of the northeast section of the city of	Do.
	10.	Scranton	Do.
	11.	the city of Scranton.  Mine workings under a part of the North Providence section of	Do.
	12.	the city of Scranton	Do.
	13.	city of Scranton.  Mine workings under a part of the Leggetts Gap section of the	Do.
	14.	city of Scranton	Do.
		of Scranton.  Mine workings under a part of the west section of the city of	Do.
		Scranton.  Mine workings under a part of the Hyde Park section of the city	Do.
		of Scranton.  Mine workings under a part of the Hyde Park section of the city	Do.
		of Scranton.  Mine workings under a part of the central section of the city of	Do.
		Scranton.  Mine workings under a part of the south section of the city of	Do.
		Scranton	Do.
		Scranton	Do.
		Scranton	Do.
	44.	Mine workings under a part of the southeast section of the city of Scranton	Do

PLATE	23.	Mine workings under a part of the southeast section of the city of	Page.
		Scranton	In case,
	24.	Mine workings under a part of the east section of the city of	
		Scranton	Do.
	25.	Index map of the city of Scranton	Do.
	26.	A, Gangway cut through culm flushing, Oxford mine; B, Gang-	
		way cut through flushing, culm standing as a vertical self-sus-	
		taining wall, Oxford mine	52
	27.	A, Timber and rock cog in Bellevue mine; B, Gob pier in Dun-	
		more No. 2 bed, National mine	52
	28.	A, Gob pier in Clark bed under Central High School building,	
		Pine Brook mine; B, Similar pier with flush pipe passing	
		through shows superficial character of mortar pointing	54
	29.	A, View in squeezed area in Dunmore bed, Leggetts Creek mine;	
		B, Sandstone and cement masonry pier in Dunmore No. 2	
		had under School No. 15 National mine	54

### PREFACE.

### By Joseph A. Holmes.

The perpetuation of the supply of anthracite coal in Pennsylvania is a national as well as a State problem. Any investigation that shows how larger percentages of this coal may be saved in mining, without excessive cost, and without dangerous subsidence of the overlying surface ground, has a national as well as a local interest.

Messrs. Conner and Griffith, who conducted the investigations described in this report largely for the city of Scranton, are consulting engineers for the Bureau of Mines for investigations similar to those they have already made in connection with their Scranton work; and this report is published by the bureau in response to numerous requests, because of the fact that the information it contains will prove useful in the general solution of similar problems in many of the country's coal fields.

A study of the accompanying maps will show that the city of Scranton is underlain by 11 separate beds of coal, varying in thickness from 2 to 24 feet. It is estimated that before mining operations were begun these beds of coal contained underneath the present city limits of Scranton 600,000,000 tons of coal. The 27 collieries operating within the city limits, working independently of each other, had excavated and removed, up to March, 1911, an aggregate of 198,000,000 cubic yards of coal and accompanying rock, or 3,000,000 cubic yards more than the total amount of material excavated and to be excavated by the United States in constructing the Panama Canal. This fact illustrates something of the magnitude of the problem that the city of Scranton, with the aid of these engineers and of a special commission or advisory board, has undertaken to solve. The excavation has included 177,000,000 tons of coal and 44,000,000 tons of rock and accompanying refuse. This leaves about 420,000,000 tons of coal still to be removed.

As a result of other investigations and of experience in adjacent anthracite mines, Messrs. Conner and Griffith and the advisory board of engineers have advised that, as far as may be necessary to prevent dangerous surface subsidence, the spaces remaining beneath the city of Scranton from the excavation of the above-described material should be filled with sand and other materials by flushing or other processes. This operation is expensive, but it is believed to be not beyond the reach of what is practicable, nor in excess of the value of the coal that may be removed and the amount of damages that may result from the caving in of the surface if such a plan is not carried out.

No one realizes so fully as do the authors of this report the need of additional tests and other investigations before the data now presented by them can be fully accepted as sufficient for all purposes in the solution of the problem; and it is expected that at some early date a more extensive series of similar tests can be made by the Bureau of Mines under the supervision of Messrs. Conner and Griffith

on a larger scale and under a greater variety of conditions.

The field examinations made for the Bureau of Mines by N. H. Darton, which are described briefly in a chapter of this bulletin and will be discussed at length in a bulletin to be published later, indicate the extent and distribution of the sands, gravels, and other materials in the Scranton-Wilkes-Barre district available for flushing purposes if further tests indicate their relative merits; and it is expected that the relative merits of these different materials will soon be tested under such conditions as will furnish the desired information.

### MINING CONDITIONS UNDER THE CITY OF SCRANTON, PA.

By WILLIAM GRIFFITH AND ELI T. CONNER.

### LETTER OF TRANSMITTAL.

To the honorable Mayor and Council of the City of Scranton, and to the Board of Control of the Scranton School District:

Gentlemen: In rendering to you the following report upon the mining conditions under the city of Scranton, with observations and recommendations for the amelioration of the same, we feel that an apology is due for the voluminous proportions of the document. We trust, however, that you will consider the magnitude of the subject, and the manifest necessity under the circumstances of sacrificing brevity for clearness.

We have considered all the phases of the question in hand as fully and thoroughly as possible, having not only exhausted all the sources of present information available to us, but having made many tests and experiments as to the strength of materials and the efficiency of roof-supporting devices, both those at present in use and those originated by us. We may, therefore, perhaps be pardoned for felicitating ourselves with the consciousness that the whole question has been investigated and is herein considered with all the completeness which our ability and limitations would permit.

We desire to express our appreciation of the pleasant and courteous manner in which all the mining companies, including managers, superintendents, and inside officials, and the officials of the Fritz engineering laboratory of Lehigh University, have assisted us during the progress of the investigation, for without this cordial cooperation this report could not have been submitted in its present completeness. Our acknowledgments are also due to and on account of the treatment accorded us by the officials of the city and board of control, by the press and the public, and to Mr. S. N. Callender, for the use of his copy of the city atlas. Also to the members of the advisory board, for the care and enthusiasm with which they have considered this report, and for their practical suggestions, which are incorporated herein.

Very respectfully,

WM. GRIFFITH, ELI T. CONNER.



### SUMMARY.

We would summarize our findings as follows:

The report is accompanied by plates which present a full set of plans of the city of Scranton and the mine workings thereunder, and also cross sections showing the positions of the several beds of coal and the intervening strata. From these plates one can readily determine, at almost any given point, the depth of the coal below the surface, the thickness of the beds, and the thickness of the intervening strata, since all of the plans are drawn to scale. These plates should be carefully studied in connection with the report and tables. As provided for in our contract, these plans are based upon information obtained from the maps, records, and data loaned to us by the several mining corporations, the Pennsylvania geological survey of 1885, and from our own personal investigations and measurements.

It will be noted that the coal basin underlying the city is wide and comparatively shallow, so that the coal beds and the intervening strata are comparatively flat, by reason of which fact the artificial pillars that may be inserted are not at all liable to slip or move on account of the dip of the seams. The only part of the coal measures underlying this city where there is an excessive dip is along the West Mountain, where pitches as steep as 50° are found. There is only a small part of the surface underlain by such pitching seams that carries important improvements, namely, in the vicinity of No. 23 School and what is locally known as the "Notch."

After about 40 days of careful inspection of underground conditions at all of the collieries operating within the city limits, we find that the total quantity of coal and refuse that has been extracted under the city of Scranton is about 221,000,000 tons.

There has been produced for market from the 27 collieries, 177,000,-000 tons of coal.

The space excavated under the city is about 198,000,000 cubic yards. The total estimated excavation by the United States for the Panama Canal is 195,323,000 cubic yards.

It must not be understood that the hole from which the above material has been taken is still open. It is, of course, impossible to say what percentage of the space excavated remains open, but we would express the belief that it does not exceed one-half of the original, due to the numerous squeezes and cave-ins that have occurred.

After spending more than 40 days' time studying maps, after testing various materials used and considered for roof support in the

mines, and after tabulating and considering the information gained by these investigations, the conclusions we have reached are as follows:

Although some other devices are locally useful, the only method that combines the necessary qualities of strength, ease of application, and reasonable cost is filling the underground openings by what is known as the "flushing" method, using for flushing culm, sand, crushed rock, and other fine material that can be washed into the mines with water. This method was originated in the anthracite region of Pennsylvania, and has been extensively adopted in European mines, where, at great expense, sand, loam, and crushed rock are flushed into the mines following the removal of the coal by the longwall method of mining.

The tables and estimates of cost contained in the body of the report give in detail the results of our investigations and conclusions.

We therefore offer as our only recommendation that the flushing method be adopted, under the plans and specifications contained in the body of the report and in plates 1 to 24. From the report the following general conclusions are drawn:

1. Speaking broadly, the surface of the city can be supported by the methods recommended, and at a cost not in any sense prohibitory when considered with relation to the value of the property and operations for which support is absolutely essential.

2. Although in our judgment there are points in the city, as indicated in the detailed report, where at the present time there is distinct and immediate danger to life and property, yet the total area immediately threatened constitutes but about 15 per cent of the entire area of the city, and the danger is mainly from workings in surface beds.

3. On the west side the beds of the middle series are thick and close together, and the pillars are not columnized, creating a dangerous situation where the workings have not been closed by previous caves. Particular areas thus threatened can not be definitely specified on account of the inaccessibility of much of the mined-over area. Detailed investigation should be made of the portions of the mines not already closed. Relatively, we do not believe that a large part of the territory mentioned is threatened on account of so much ground having been already closed by caves.

Special attention is called to the conditions under schools Nos. 13, 23, and 29. They should be attended to promptly.

The lower series of beds, namely, the three Dunmores, are so thin and so far below the surface that with the usual system of mining we do not think they constitute a serious menace to the improvements on the surface, except along the margin of solid blocks of unmined coal and near the outcrops. In the deep-lying parts of the Dunmore beds we believe these solid blocks should be mined.

- 4. It would seem, therefore, to be not only the part of wisdom, but absolutely obligatory, to immediately commence supporting the points menaced, and thereupon proceed upon a general policy of giving support to the entire area of the city, for it must be borne in mind that with the mining activities that are constantly going on other and additional points of danger are not only liable to, but in all probability will, develop with each passing year—it might almost be said with each passing month.
- 5. Where the owner of the surface has undoubted right to the support thereof by coal pillars, in our opinion he could permit the removal of such pillars; the value thereof would under average conditions pay for such artificial support as we have recommended, if it be assumed that the pillars were mined and the support constructed by the same operating company. This observation, however, is based upon the assumption that in such case the operating company is one of the large transportation companies, inasmuch as although there might not be a profit in the immediate transaction of mining the pillars and installing the support, there would, of course, be a profit to such companies in carrying the coal to market.

6. Culm flushing should be used only in coal beds having light cover, up to 200 to 500 feet, according to the settlement expected. But sand, being four or five times as strong as culm, is better, and, being suitable for filling all beds under Scranton, is to be preferred.

7. We believe that the conclusions adduced from the tests made, and the calculations and tabulations based thereon, are reasonably reliable; yet we desire to record the opinion that there are conditions existing in the mines to which they might not apply. Such might be the case, for instance, in localities where several beds of coal are separated by thin strata of shale and slate or even sandstone, and the pillars in the two or more beds are not over one another, and it is proposed to reclaim all or any part of the pillars.

Even though an application of the above-mentioned tables might appear to fit the conditions, we believe that the only permissible procedure would be to first fill with flushed material all of the openings in the lowest bed of the series, and then fill upward until all the beds are filled, care being taken to have the flushed areas over one another. After all of the openings in all of the beds have been filled the pillars in the uppermost bed may be attacked, and the space occupied by each pillar filled as soon as the pillar is removed. No pillar reclamation should be permitted in any of the other beds until all of the pillars in the upper bed have been removed and the overburden has come to rest on the flushed material; after which the pillars in the next lower seam may be attacked and handled in like manner.

8. Harmonious plans and procedure between the coal companies, the city, the school authorities, and the public are essential to the

successful carrying out of any relief measures that are herein or may be hereafter suggested. Some facts that should be evident to all are that the prosperity of the city and of the community is to a large extent dependent upon the coal companies; that drastic laws or regulations that may curtail the mining of coal will necessarily react on the prosperity of the community; and that any ameliorating plans or compromises which it may be possible to effect between the city and the mining companies tend to prolong the life of the mining industry in Scranton and vicinity, and should be promoted.

It should therefore be the aim of all interested in mine-cave protective measures and of the companies operating the mines to adopt plans that will best conserve the welfare of all interested.

The expenditure for the work would of course be distributed over many years, the relief measures being applied at the points most in need of protection and as rapidly as proper arrangements could be effected and the necessary details, surveys, etc., prepared.

For the businesslike carrying out of the plans suggested it is recommended that a protective commission be established, consisting of not less than three nor more than five men, representing the city authorities, the school board, and the coal companies—this commission to have full and complete authority for the execution of the plans, and to be approved by the proper legal action. The commission should employ an engineer who should devote all his time to the service as active manager of the work.

### THE REASON WHY.

The occasional mine caves or settlements in various parts of Scranton during the past years had long caused more or less public concern, until finally popular sentiment was brought to a focus by the settlement in Hyde Park, on August 29, 1909. This subsidence seriously damaged public school No. 16 and much other surrounding property; and, if it had occurred while school was in session, might have been the cause of loss of life.

Immediately following this event committees of councils, board of control, and board of trade took action in an endeavor to discover the immediate physical causes of the caving, as well as the legal responsibility therefor; and after much consideration, the former mayor, Hon. J. B. Dimmick, who was called in consultation with the joint committee, proposed the plan as set forth below and quoted from his final report, to wit:

To the joint committee of mine caves of select and common councils and of the board of control, Benton T. Jayne, chairman:

Gentlemen: I beg leave to herewith make report of what I have been able to accomplish in pursuance of your instructions looking to the selection of an engineer to be employed by the city and the board of control for the purpose of making a study of

the physical aspect of the entire mine-cave problem as it affects our city, and to make a report thereon together with such recommendations as would seem fitting and practicable.

Shortly after I received your instructions I laid the entire situation before John Hays Hammond, the well-known engineer, and he at once not only became deeply interested in the problem but offered his aid and assistance without compensation, direct or indirect, being moved simply by a willingness to perform public service.

After much thought and conversation with the gentlemen whose names are hereinafter given, the following definite plan has been worked out and awaits but acceptance upon the part of the city government and the board of control.

### PLAN.

An advisory board has been formed consisting of five well-known engineers, with power to add to their number, namely: John Hays Hammond, D. W. Brunton, R. A. F. Penrose, jr., Lewis B. Stillwell, and W. A. Lathrop, this board having all agreed to act without compensation.<sup>a</sup> After a careful investigation of the necessary qualifications of the engineers that would make the actual study upon the ground, they suggested the names of Eli. T. Conner, of Philadelphia, Pa., and William Griffith, of Scranton, Pa., Mr. Conner having had considerable experience in anthracite-mining operations, and Mr. Griffith being especially informed as to the geological formation of this section. These two engineers to be employed by the city and the board of control, and upon the filing of their report, the same to be carefully considered and passed upon by the advisory board.

In order that the matter might be in complete form for your consideration, I secured from the two engineers, as recommended, a definite proposition, which is herewith incorporated in extenso:

SCRANTON, PA., May 25, 1910.

Hon. J. BENJ. DIMMICK, Scranton, Pa.:

As a result of our conference with you yesterday, in accordance with your request made at that time, we respectfully submit the following:

Of course, it is recognized by everybody that the situation is serious regarding the mining conditions under portions of the city of Scranton, and the proposition of proecting the whole city can best be met by a frank recognition of the varying conditions that undoubtedly exist, certain sections of the city being really in danger, while others are, practically speaking, not menaced. While our proposed report would be general in character, and intended to cover the entire city, yet it would properly be especially concerned with those sections of the city that are immediately threatened.

It seems to us that what is most necessary at the present time is more accurate knowledge of the physical conditions which now prevail, and we would suggest a report based upon the results of a careful study of such physical conditions as they at present exist in the mines under the city of Scranton; this report to be general in its nature. We would group together the various similar conditions in several classes, to each of which similar remedies or lack of remedy might apply, with suggestions not only as to remedies but also as to the approximate cost thereof under certain ascertained conditions. We should expect to also include in said report such general observations and recommendations touching the entire situation as would seem to be justified by our inspection and study thereof. The completeness and value of any such report would depend in a large measure upon the assistance and cooperation tendered us by the several mining companies who are now operating under the city and of the city and school authorities.

a The advisory board subsequently included the following additional members: Dr. H. S. Drinker, president of Lehigh University; Dr. J. A. Holmes, director of the Bureau of Mines; Prof. J. F. Kemp, Columbia University; Prof. J. F. McClelland, Yale University; and Prof. H. L. Smyth, Harvard University.

It is to be distinctly understood that such proposed report and study of the situation existing under Scranton would be based upon such information as might be obtained from the second geological survey and from such other maps of the various coal-mining companies and the city and school authorities, to which access could be obtained for the engineers, and from such personal inspection of accessible portions of the mines as, in our judgment, shall be necessary. We would, however, give expression to our belief that such surveys are sufficiently accurate and reliable as a basis for the general conclusions that the report will be expected to set forth.

It seems to us that the information to be secured through such a report would be the first requisite to a subsequent detailed investigation and application of any remedies which might be suggested for the amelioration of the mining conditions under this city.

Yours, respectfully,

(Signed) WM. GRIFFITH, ELI. T. CONNER, Mining Engineers.

It therefore remains but for the community, through its city government and the board of control, to employ these two engineers at the price stipulated in order to receive a general report upon the cave problem that should command the respect and the confidence of all parties interested, not only because it will have been prepared by engineers selected by a board composed of experts of national reputation, but also because the very findings of such engineers would, in their turn, be submitted to and reported upon by that same advisory board. In short, the community would then be provided with information as to facts and opinions as to remedies that would form solid ground for both future deliberations and future activities.

I can not refrain from suggesting, assuming the acceptance of this most unselfish offer upon the part of men of high professional equipment and without personal interest in the welfare of Scranton, that, simultaneously with the enactment of the necessary legislation to carry into effect this plan, there should be official appreciation of their proffered assistance.

Respectfully submitted.

J. BENJ. DIMMICK.

Certified copy.

EVAN R. MORRIS, City Clerk.

SEPTEMBER 15, 1910.

### GEOLOGY.

The city of Scranton occupies the surface overlying the whole width (5 miles) of the Lackawanna coal field, and extends about 5 miles up and down the valley. The central part of the city is over the center of the coal basin, while the margin of the basin on the East and West Mountains nearly coincides with the city line along those hills.

The floor of this coal basin is formed by the hard Pottsville conglomerate or "pudding stone," which comes to the surface on the mountain sides east of Roaring Brook, and dipping down under the surface in the form of a deep trough or basin passes under the central part of the city at a depth of several hundred feet, and again reaches the surface on the flanks of the West Mountain. Passengers on the Laurel Line can note this conglomerate on both sides of the Roaring Brook ravine and at the stone quarry on the east near the switch where the Dunmore branch leaves the main line.

HISTORY. 15

It is the conglomerate that forms the roof of the Lackawanna tunnel at Nay Aug, and is again cut by this railroad on the west side of the valley, at Leggetts Creek Gap.

As before stated, this rock forms the floor of the coal basin. No coal exists below it; therefore all the coal under the city of Scranton is to be found in the rocks which fill this trough or basin and overlie the Pottsville conglomerate. The coal is deposited in parallel layers or beds, known locally as "coal veins," that are approximately parallel to the conglomerate floor, and lie deepest in the central part of the basin. They extend with persistence and considerable regularity from outcrop to outcrop, except where they were removed with other rocks during the surface erosion of past ages.

In all, there are 11 principal coal beds under this city, known by names as follows, beginning with the highest:

The Eight-Foot coal bed, which is present only in two small areas or islands under the highest part of the Hyde Park hill.

The Five-Foot and Four-Foot beds, which are only in the hill top on the west side from Dodge to Marvine, above the level of the Lackawanna River.

The Diamond and Rock beds, which are on the west side only of Lackawanna River, under Bellevue, Hyde Park, Providence, and parts of Keyser Valley.

The Big or Fourteen-Foot and New County beds, which extend under the whole west side, and also become surface beds on the east side at the National colliery, near the south line of the city; also under the central city and hill section, nearly to the Moses Taylor Hospital.

The Clark, Dunmore No. 1, Dunmore No. 2, and Dunmore No. 3 beds, which extend under the whole city from Nay Aug Park to the West Mountain.

For the thicknesses of these several beds, the distances between them, and their relative positions in the coal measures, the reader is referred to the columnar section sheets contained in Plates 1 to 24 of this report.

### HISTORY.

### EARLY DEVELOPMENTS.

The late Dr. B. H. Throop reported to an industrial convention at Tunkhannock, in the year 1842, that the Lackawanna Valley from Archbald to Pittston "contains upward of one hundred coal mines opened, and many of them are made at present a source of profit both from domestic and foreign markets. There are sent some five or six thousand tons of coal annually by sledges and wagons to the States of New York and New Jersey, in exchange for salt, plaster, etc."

In 1841 the first furnace of the Lackawanna Iron & Coal Co. was filled and fired, and though this effort to manufacture iron from local ores proved a total failure, it nevertheless gave a decided impetus to the coal-mining industry of this locality. Subsequently iron ore and limestone were brought from a distance, and anthracite was successfully used for smelting iron. Since this beginning the coal industry of Scranton has continuously flourished until the present.

The mines worked by the iron company in 1841 were on both sides of Roaring Brook. The Clark bed was worked near the viaduct; later the Dunmore beds were worked near the site of the present Laurel Line power house by what were known as the Rolling Mill drifts. For several years these were the principal mines in Scranton.

In 1851 the Lackawanna & Western Railroad was built from Scranton to connect with the Erie road at Great Bend. The Delaware & Cobbs Gap road (chartered in 1849) was merged with the Lackawanna, and in 1856, under the name of the Delaware, Lackawanna & Western Railroad, was built through from Scranton to the Delaware River. In 1858 the Lackawanna & Bloomsburg road was built. Equipped thus with new and permanent outlets for its resources, the mining industry of the valley and the city advanced with rapid strides.

About 1852 the Diamond mines were opened. In 1854 the Rock-well mine at Leggetts Gap, and the Bellevue colliery were opened. The opening of numerous other coal operations followed in rapid succession.

### MINING METHODS.

The room and pillar system of mining was adopted in these old mines, and has been continued in all the mining of the region to the present time. This method consists, briefly, in driving an airway and a gangway about 15 feet apart and parallel in the coal bed. the high side—that is, to the rise—chambers or rooms are driven parallel to each other and at right angles to the gangways. The rooms are about 30 feet wide and are separated by partitions about 15 feet in thickness called pillars. The coal production of the mine is mainly taken from the contents of the rooms; the pillars, which comprise approximately one-third of the coal, are left to support the surface. This practice of leaving one-third of the coal for surface support was adopted at the start, and was found sufficient for the comparatively light overburden to be sustained in the mining of the beds near the surface. It has been continued as an empirical rule with little variation, in the deeper mining under the city, without reference to the weight on the pillars or the strength of the coal.

In the past the several beds of each mine were worked independently of each other and no attempt was made to regulate the size,

position, and distribution of pillars aside from the one-third rule. Consequently, the pillars are not columnized; in other words, they are not exactly over each other. Many of the thick beds of the middle measures under the Hyde Park and Providence sections are close together. Therefore the pillars in these thick beds, not being columnized, have a decided tendency to crush through the interval between the beds, the pillars of an upper bed settling into the excavations or rooms of the lower workings.

Another feature that should be brought out in this historical sketch of early mining in Scranton is that the universal practice in the old days was to mine only the best, thickest, and most accessible coal beds, and also only the profitable parts of each bed, and to leave unmined, as refuse, the parts which for one cause or another were found more expensive to work. Therefore, in these latter days some of the coal beds already mined over and ready to be abandoned have been found to carry rider coal above or bottom coal below, which can be removed at a profit. And, therefore, for the past few years the total production from several beds has been from such remining of top and bottom coal. This remining, of course, leaves the pillars from 2 to 6 feet taller than they were before for the same horizontal area, consequently the pillars are much weaker and less able to support the overburden.

In consequence of the several conditions related above there have been from time to time numerous and more or less serious caves or subsidences of the surface, principally on the west side, which have caused some damage to surface property, but no loss of life. In every instance the damage has been speedily repaired and temporarily forgotten. The accumulated result of these repeated subsidences has probably left certain parts of the surface in that section of the city in more stable condition than they were before. This phase of the subject, however, will be considered in a subsequent chapter.

### STATISTICS OF COAL PRODUCTION.

The following statistics of the coal-mining industry in Scranton are based upon the result of the surface and underground investigations made by us, and from our inspection of the mine maps, taken in conjunction with the annual production of coal as shown in the published statistics contained in the reports of the State mine inspectors.

Table 1.—Total production of coal mined under the city of Scranton, 1841-1910.

Year.	Production.	Year.	Production
1841–1872. 1872. 1873. 1874. 1875. 1874. 1875. 1876. 1877. 1878. 1879. 1880. 1881. 1882. 1883. 1882. 1883. 1884. 1885. 1887. 1887.	2,155,647 2,570,081 1,630,158 2,312,580 1,572,033 1,818,867 1,732,782 2,670,629 2,477,285 3,002,761 2,996,795 3,280,001 3,038,291 3,061,483 3,092,069 4,474,419 4,474,419 3,724,127 1,682,073	1892. 1893. 1894. 1895. 1896. 1897. 1898. 1899. 1900. 1901. 1902. 1903. 1904. 1905. 1906. 1907. 1908.	3,992,64 3,614,48 4,042,67 3,832,84 4,389,55,90 3,527,82 4,388,33 4,381,57 6,041,21 6,578,77 6,202,69 6,257,38 6,163,364,25 6,163,364,72 6,948,25 6,163,367,25

TABLE 2.—Statistical table of coal mining.

Coal beds.	Average thick- ness of beds.	Origi- nal area before mining.	Area mined over.	Area to be mined.	Approximate area of pillars.	Area of mine excavation.	Foot- acres mined over, includ- ing pillars.	Foot- acres exca- vated, exclud- ing pillars.	Foot- acres to be exca- vated, leaving one-third for pillars.
Eight-foot		Acres. 140 2,000 2,460 4,160 4,160 4,500 6,000 5,360 7,860 7,500 9,630 8,500	Acres. 111 1,093 994 3,562 3,000 4,831 1,549 6,040 690 2,533 1,573	Acres. 29 907 1,466 598 1,500 1,169 3,811 1,820 6,810 7,097 6,927	Acres. 35 364 331 1,187 1,000 1,610 516 2,013 230 844 524 8,654	Acres. 76 729 663 2.375 2.000 3.231 1,033 4.027 460 1,689 1,049	843 4, 809 3, 578 33, 495 15, 600 58, 938 9, 294 40, 468 2, 070 10, 132 5, 191 184, 418	577 3, 208 2, 387 22, 325 10, 400 39, 296 6, 198 26, 981 1, 380 6, 756 3, 462	146 2, 660 3, 518 3, 746 5, 200 9, 508 15, 244 8, 130 13, 620 14, 194 15, 240

### PRESENT MINING CONDITIONS UNDER SCRANTON.

The following tabulated notes give in condensed form the actual conditions of the mining under the city and school properties at present, as found by your engineers during an extended underground inspection that lasted about 40 days.

In connection with these notes the plates accompanying this report should be well studied. These plates set forth in a more intelligible form than can possibly be shown by words the location and extent of the mining in all the coal beds under the city, and by plans, cross sections, columnar sections, etc., clearly indicate the geology and distribution of the beds throughout the measures.

### Scranton Coal Co. collieries.

## PINE BROOK COLLIERY.

(Works central city section from the river to Nay Aug and from Poplar Street to Beech Street.)

S. General conditions.	Eroded.	Do.	Do.	Do.	Do.	<ul> <li>knightreport.)</li> <li>53 acres mined over. Depth. 30 to 50 feet (see sections on Pls.</li> <li>2. 3. 4. and 5); thickness. 12 to 16 feet; pullars sound where observed. local falls; old workings mainly fallen and inacessible.</li> </ul>	Not mined; 3 feet thick.	in o evidence of imputities; depth. 150 to 200 feet. (See sections on Ples. 2, 3, 4, and 5). Character frible, pillars subject to chipping. Old workings between fribsen and and Ash Sireets and from Capouse to Quinca Arenue show weakness due to weight, and indicate incipient squeeze. Old Iron Co. workings both sides Roaring Frook. North Side bounded by Markison. Viene and Glay Streets and the brook. South workings side tying between the brook and littsion Avenue are inaccessible. The bud is near surface and thick, and old maps show very small pillar support.	tions good.  349 acres mined over. Bed 4 to 5 feet thick: some places increased f rock.  by top bench: bottom taken up for height: chambers partly filled with rock; general conditions good: depth, 200 to 270 feet (see sections on Pls. 1, 2, 3, 4, and 5).
Mining conditions under school properties.	Broded	do	do	do	do	Inaccessible butreported flushed. (See Stevenson and Knight report.) Near outerop; probably unminable or absent Partly mines believe in the prosts and gob stoppings, behind which inaccessible; reported filled. (See Stevenson and Knight report.)	Not mined.	Pillars sound, as shown on maps; not much chipping; no evidence of disturbance.  Pillars sound and no disturbance.  Pillars sound and undisturbed; chambers filled with dry ashes.  Chambers large all pillars small and weak; nor fallen in all chambers.  Pillars sound and undisturbed; chambers filled with dry ashes.  Pillars sound and undisturbed; small and apparent weakness shown by chipping; gob piers huilt; flush pipe passes under and heyord school.  Filled with water and inaccessible.	Chambers nearly filled with rock; pillars strong; conditions good.  Inaccessible on account of water; reported partly full of rock.  Chambers nearly full of rock; pillars sound; conditions good.  Pillars large; only partly mined; conditions good.  Chambers nearly filled; conditions good.
Name of school.						Technical High No. 33 Central High		No. 4. No. 9. No. 33. Technical High Central High No. 36.	No. 4. No. 9. Technical High. Central High. No. 33. Nos. 35 and 36.
Coal beds.	Eight-foot	Five-foot	Four-foot	Diamond	Rock	Big.	New County	Clark	Dunmore No. 1

Seranton Coal Co. collieries—Continued.

## PINE BROOK COLLIERY-Continued.

No. 36.  No. 36.  No. 37.  Inares sound and large. No. 37.  Inares sound and large. No. 37.  Pillars sound: conditions good. Now working. Technical High.  Pillars sound: conditions good. No. 38.  Pillars sound: conditions good. No. 38.  No. 38.  No. 3.  No. 3.  Old workings: recently filled: conditions good. No. 30.  Pillars sightly chipped: otherwise strong, and as per map; three-fourths of space outside of roadway filled with gob; conditions good.  Central High.  No. 30.  No. 30.  Pillars slightly chipped: otherwise strong, and as per map; three-fourths of space outside of roadway filled with gob; conditions good.  No. 30.  Pillars slightly chipped: otherwise strong, and as per map; three-fourths of space outside of roadway filled with gob; conditions good.  Not now mined, but being extended; near-by workings three-fourths rock being taken down and workings three-fourths rock being good.  Pillars sound: chanbers three-fourths filled outside of road; conditions good.  Pillars sound: chanbers three-fourths filled outside of road; conditions good.	dis-  S22 acres mined. Bed 3 to 5 feet thick; 1 to 2 feet of hottom raised or theight; chambers nearly filled with gob, except read in center; pillars strong and conditions generally good, except old Robing Milled fifth and slope which sides of Roaring Frook, where pillars are small and openings large.  See sections on Pls. 1, 2, 3, 4, 5, 18, 22, and 24.)  Inceptual Bed 23 to 5 feet thick, including 10 to 18 inches three conway in center; pillars strong and conditions generally good; depth, 300 to 350 feet (see sections on Pls. 1 to 24).
--	---

### MOUNT PLEASANT COLLIERY.

(Works Hyde Park, from Lackawanna River to Keyser Creek, and between Lafayette and Petifibone Streets.)

	The same of the sa	A Comment	The second of th
Eight-foot	No. 18	School over outcrop of bed; bed not mined	33 acres mined. Depth, none at outcrop to 80 feet over center of area (see Pls. 14, 16, and 17), thickness, 8 feet 8 inches in center; 1 foot 5 inches relias; all mined over, except stripping at outcrop, and abandoned; pillars standing in good condition.
Five-foot	.do.	Depth, 134 feet; openings filled with gob and falling fire clay; pillars reported standing firm, reinforced by this falling strata shaken by old squeeze in lower beds; present conditions fair.	122 acres mined. Depth, none at outerop to 200 feet (see sections on Pis. 14, 19, and 17); thickness, 5 feet 8 factors, includes 10 inches of bone at top; bed overlaid by 3 feet 5 inches of failing free clay; all abandoned parts filled with failing free clay; all abandoned parts filled with failing free clay;
Four-foot.	do	Depth, 164 feet; pillars large and firm; rooms filled with rock	120 acres mined. Depth, see sections on Plates 14, 16, and 17; twin bet; top conf. 1 foot 10 inches; dividing rock, 6 to 7 feet; bottom coal, 3 feet; pillars sound; rooms filled with rock; conditions good.
Diamond	do.	Mined, closed, abandoned, and inaccessible; depth, 280 feet	188 acres mined. Depth, see sections on Plates 14, 16, and 17; thickness about 10 feet; soft falling roof, workings formerly squeezed; a now closed by falling rock and inaccessible.
Rock	do	Mine abandoned and inaccessible account falls and old squeeze; depth, 315 feet.	190 acres mined. Depth, see sections on Plates 14, 16, and 17; thick-ness, 7 to 8 feet, 1 foot 2 inches refuse; reported pillars more than 33 per cent, but mine closed and inaccessible on account of squeeze, a
Big	do	Depth, 376 feet; workings inaccessible on account of roof falls, but pillars reported large and not crushed. (See maps.)	214 acres mined. Depth, see sections on Plates 14, 16, and 17; thickness, 14 feet 9 inches; 1 foot 7 inches refuse; workings partly open, but mainly closed by local falls and old squeeze.
New County	do	Partly mined; rooms filled with rock; remaining coal soon to be mined, leaving usual pillars; depth, 418 feet.	208 acres mined. Depth, see sections on Plates 14, 16, and 17; thickness, 9 feet 8 inches, includes 1 foot 10 inches of refuse; open and accessible; rooms partly filled with gob; pillars sound, usual size; conditions good.
Clark	do.	Substantial pillars, some chipping, no indication of settlement; depth, 481 feet.	202 acres mined. Depth, see sections on Plates 14, 16, and 17; thickness, 6 feet 5 inches, includes 8 inches of refuse; rooms wider pillars slightly air chipped, but otherwise sound; conditions fair.
Dunmore No. 1	do.	Depth, 598 feet; only partly mined, by two gangways; no chambers.	32 acres mined. Depth, see sections on Plates 14, 16, and 17; thick-ness, 1 foot 4 inches to 1 foot 8 inches; vein too thin for profitable mining and now abandoned; openings filled with gob; conditions good.

a Surface subsidence may and often does occur where pillars are strong, and without much warning or crushing of pillars, if conditions exist such as those under Hyde Park, where many thick beds lie close together and the pillars in the several beds are not columnized; pillars of an upper bed are thus permitted to break through the intervening strata into the chambers or openings of an underlying bed.

## Seranton Coal Co. collieries—Continued. MOUNT PLEASANT COLLIERY—Continued.

		MOCKLI LEANERNI COLLIENT COMMING	
Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Dunmore No. 2	No. 18.	Depth, 612 feet; large pillars, sound and undisturbed; rooms nearly full of gob.	92 acres mined. Depth, see sections on Plates 14, 16, and 17; thickness, 4 feef 3 inches, rooms nearly full of got; conditions good; at northwest end of property vein too thin to mine at present.
Dunmore No. 3 do	ор.	Pillars sound, of usual size; chambers partly filled; depth, 704 feet. 115 acres mined. Depth. see sections on Plates 14, 16, and 17; thickness, 4 feet 3 inches, includes 1 inch slate and hone top; rooms nearly filled with gob; floor raised for height.	115 acres mined. Depth, see sections on Plates 14, 16, and 17; thickness, 4 feet 3 inches, includes 1 inch skite and bone top; rooms nearly filled with gob; floor raised for height.
	). (WG	CAPOUSE COLLIERY. (Works Keyser Valley from Keyser (Teek to outcrop and from Jackson Street 1 mile northeastward.	reet. 1 mile northeastward.)
Eight-foot		Eroded	Eroded.
Five-foot		ор.	Do.
Four-foot		op.	Few surface improvements.
Diamond	No. 17.	Depth, 92 feet; inaccessible under school on account of removal of surrounding pillars, but under school for area of 200 feet square pillars reported sound and still standing.	262 acres mined. Depth, see sections on Plates 12, 13, and 14; thickness, 10 feet; workings have been remined, and pillars removed over a large area; mining in Diamond bed has ceased.
Rock	do	Depth, 136 feet; inaccessible for reason stated above; similar conditions prevall; mearest accessible point 400 feet from school.	193 acres mined. Depth, see sections on Plates 12, 13, and 14; thickness, 3 feet 10 inches; rooms two-thirds filled with gol; partly remined and inaccessible.
Big	do	Depth, 216 feet; pillars as shown on maps; sound, except slight chipping; local falls in rooms under school.	317 acres mined. Depth, see sections on Plates 12, 13, and 14; thickness, 13 feet 3 inches, includes 9 inches refuser local falls; no remining as yet; few improvements on surface.
New County	ор	Depth, 246 feet; rooms two-thirds filled with gob; also local falls; pillars good; no indication of settlement.	100 acres mined. Depth, see sections on Plates 12, 13, and 14; thick ness, 6 feet 8 inches, includes 2 feet 11 inches of refuse; rooms two-thirds fuled with gob; numerous local falls in chambers; no indication of present settlement; remining near outcrop.

Dunmore No. 3do		
	Depth, 380 feet; pillars sound, usual size; rooms nearly filled with gob; 139 acres mined. conditions good.	139 acres mined. Depth, see sections on Plates 12, 13, and 14; thickness 5 feet Furches, includes inches refuse; bottom raised for height, no falls, rooms filled with gob, except roadway; conditions good.
	Depth, 480 feet; not mined.	55 acres mined. This we'n not being mined; too thin for profitable mining at present.
	WEST RIDGE COLLIERY. (Works Providence section, North Main Avenue to outcrop between Putnam and Clearview Streets.)	ann and Clearview Streets.)
Fight-foot.	Broded	Eroded.
Five-foot No. 40	Depth, 66 feet; workings inaccessible; approached to point about 300 feet from school; workings filled with falling fire-clay roof; workings now controlled by Clearview Coal Co.	stacres mined. Depth, see sections on Plates 2, 7, 11, and 13; thickness, 4 feet clear; roof falling: 34 to 4 feet of fire clay and bone that fall soon affer mining and fill the chambers; driving chambers stowed with rock from next vein below. Much of the surface is unimproved.
Top split of Four-foot.	Depth, Ss feet (see Clearview Coal Co., p. 43)	9 acres mined as separate bed. Depth, see sections on Plates 2, 7, 11, and 13; thickness, 1 to 13 inches; 3 to 4 feet of rock raised for height; all available space filled with rock and the surplus stowed in Four-foot and Five-foot beds.
Four-footdo	Depth, 118 feet. Reported formerly worked by West Ridge, but this part now controlled by Clearview Coal Co. (see p. 43).	90 acres mined. Depth, see sections on Plates 2, 7, 11, and 13; thickness, 3 feet clear coal; falling rock roof, workings filled with falling roof and rock from top split.
Diamond, Rock, Big, New County, Clark.	These beds worked by Von Storeh colliery and Delaware & Hudson (° ). (See p. 35).	See page 35.
Dunmore No. 1do	Depth, 564 feet; extensions of working here since Stevenson and Knight report; pillars sound and chambers well filled, except roadways.	36 acres mined. Depth, see sections on Plates 2.7, 11, and 13; thickness, 3 feet 1 inch, 4 inches of reduces 3 feet of bottom raised for height, rooms filled with gob, except roads; pillars sound; conditions apparently good.
Dunmore No. 2do	Depth, 616 feet; workings now extended under this school; pillars sound and usual size; rooms filled with gob, except roadway; conditions good.	43 acres mined. Depth, see sections on Plates 2, 7, 11, and 13; thickness, 2 feet is niches, 3 inches of refuse; 4 feet of bottom taken up for height; rooms, except roadway in center, filled with gob.
Dunmore No. 3 do	Depth, 686 feet; mined under school, but inaccessible on account of gas and water; conditions reported unchanged since Stevenson and Knight report.	99 acres mined. Depth, see sections on Plates 2, 7, 11, and 13, thickness, 3 feet 9 inches, including 7 inches of relates: at west end of property this bed is too thin to mine as yet; 2 to 3 feet of bottom raised for height; rooms men'ly full of rook, except roadway; first mining completed and abandoned.

## Scranton Coal Co. collieries-Continued.

## RICHMOND NO. 3 COLLIERY-BRYDEN SHAFT.

(Works center of valley. Area bounded by river, Olyphant Road, and Manville farm and narrow strip extending to East Market Street.)

Coal beds.  Eight-foot.  Five-foot  Diamond.  Bock.  Big.	Name of school.  No. 39.  do.  do.  do.	Eroded.  Eroded.  Do.  do.  do.  Do.  Do.  Do.  Do.  D	Eroded.  Do.  Do.  Do.  Do.  Do.  Not mined: depth, 109 feet under river flats; much sand and gravel, with thin rock cover over bed; too dangerous to mine.  S6 acres mined. Depth, see sections on Plate 9; thickness. 13 feet 1 inch; 2 feet 7 inches refuse, top bench not removed on first mining, now being mined; conditions fair, under river flat considerable depth of gravel and sand above the profitably mined at present.  Depth, see sections on Plate 9; not mined; too thin or dirty to be profitably mined at present.
Clark.  Dunmore No. 1  Dunmore No. 3	do	Depth, 365 feet; pillars usual size and sound except air enipping, room mad unworkable at present.  Depth, 520 feet; pillars sound and as shown on maps; rooms walled with gob on both sides of road; conditions good.  Depth, 554 feet; pillars usual size, sound and firm; rooms well filled with gob, except roadway in center; conditions good.	So acres minet. Prop. 3 se sections to a many successions. The studing 4 inches refuse pillars fook fair, but all show chipping, probably air-stacked.  Thin and not mined. At Dickson and Marville this bed is split, the upper part is known as the Dunmore No. 1 and the lower split is called the Dunmore No. 2.  76 acres mined. Depth, see section on Plate 9; thickness, 4 feet 6 inches, includes 1 foot bone on 60p. 14 feet of bottom rock taken up for height, and chambers nearly full of gob, except center roadway. This bed is known as the No. 3 at Dickson.  86 acres mined. Depth, see sections on Plate 9; thickness 4 feet 3 meres. Includes 1 foot of 1 inch refuse on top; 14 feet of bottom raised for height; rooms, except roadway, filled with gob. At Dickson and Manville this bed is known as the No. 4 or China bed.

# Delaware, Lackawanna & Western Coal Co. collieries.

### NATIONAL COLLIERY.

(Works South Scranton section, from Beech Street to city line, and from river to outcrop.)

Coal beds.  Elght-foot.  Four-foot.  Diamond.  B ig and New County.  Clark.  Dunmore No. 1  Dunmore No. 2	No. 7. No. 11. No. 10.	Eroded  do  Depth, 72 feet; nearest chamber, 60 feet from lot; now working toward school; not mined under school properties on the south side.  Not mined; too thin.  Not mined; too thin.  Depth, 165 feet; approached to within 40 feet of school; too dangerous for good under school; pillars small and weak, partly crushed; indicate incipient squeeze.  Depth, 167 feet; mortings open; pillars small but sound; openings harge; rool stools. Tool school; cool seving.  Depth, 167 feet; mortings open; pillars small but sound; openings being; poeht, 96 feet juliars very small; openings large; gob piers built:	Eroded.  Do.  Do.  Do.  Do.  Do.  Do.  Do.  D
Dunmore No. 3	No. 15.	Depth, 170 feet, mined but inaccessible on account of being litted.  Depth below cellar of school, 11 feet, shaft in school yard, through sandstone; coal pillars small, openings large, 12 sandstone and cement piers 9 feet square; conditions at present good. Thin, and not mined.	presente anns bow a magnetic under city in this bed at present.  This bed very thin; not mined.

# Delaware, Lackawanna & Western Coal Co. collieries-Continued.

### DODGE COLLIERY.

(Workings mainly in Taylor Borough. Now opening upper veins in Twenty-second ward of city.)

	Mining conditions under school properties.	Mainly croded; may perhaps be present under very small area under highest land.	Depth, about 25 feet; not yet mined; preparations to mine now in Not yet mined; thickness, 2 to 3 feet. progress.	Depth, 49 feet; not yet mined; new workings now about 150 feet Mines now being opened; depth, see sections on plate 18; thickness, from the school; chambers will soon extend under school.	All underlying beds worked from Bellevue colliery (see p. 27) Dodge colliery does not operate lower beds under this city.
	Name of school. Minin	Eroded	Depth, about 25 fe	Depth, 49 feet; no from the	All underlying bed

### HAMPTON COLLIERY.

(Works Diamond and Rock veins only. Hyde Park and Keyser Valley, west of South Main and south of Luzerne Streets.)

Eight-foot		Eroded	Eroded.
Five-foot, four-foot. No. 32 Annex	No. 32 Annex	See Hyde Park colliery, page 29	Not mined as yet (see Hyde Park colliery, p. 29).
Diamond	do	Depth, 320 feet; worked, and abandoned for a long time, but now remining for bottom coal; pillars reported sound, being remining. Depth, 28 feet; caved and inaccessible.  Depth, 291 feet; caved and inaccessible.	561 acres mined. Depth, see sections on Plates 14 to 16; thickness, about 10 to 12 feet; top bench, 6 to 8 feet, formerly mined; now remining for bottom bench, and reinforcing pillars with gob walls; much of mined area long closed by old squeeze.
Rock	No. 22 Annex No. 19	Reported inaccessible on account of caves; maps show fair pillar support.  Depth, 325 feet, caved and inaccessible.  Depth, 286 feet; caved and inaccessible.	570 acres mined. Depth, see sections on Plates 14 to 16; thickness, 94 feet, includes 3 let of refuse; long worked and mostly abandoned; bed squeezed and closed in places; now reclaiming pillars under Keyser Valley.
Big and other lower No. 32 Annex	No. 32 Annex	Mined at Central and Hyde Park collieries (see pp. 28, 29)	These beds mined by Central and Hyde Park collieries (see pp. 28, 29).

### BELLEVUE COLLIERY.

(Works Hyde Park and Bellevue sections from river to South Main Avenue, between Dodge and Oxford mines.)

Eight-foot		Froded	Eroded.
Five-foot, four-foot		See Dodge colliery, page 26.	See Dodge collicry, page 26.
Diamond	N N N N N N N N N N N N N N N N N N N	Depth 13 to 40 feet; dip about 10° NW; west two-thirds of building on solid pillar; east one-third over workings; large openings and small pillars; now remaining for bottom coal; should be properly filled.  Depth, 230 feet; inaccessible because crushed.  Froded.  Depth, 185 feet; on roll; solid under school; conditions good at Depth, 221 feet; on roll; solid under school; conditions good at Depth, 221 feet; pillars small but sound; now remining for bottom coal and stowing rock and reinforcing pillars with gob walls.	234 acres mined. Depth, see sections on Plates 15 and 17; thickness, top bench 6 to 8 freel, with 14 feet refuse; bottom bench 3 to 6 feet, about one-half refuse; top hench mined years ago and abandoned; now remining the whole area for bottom bench; pillars generally small, but sound; are now reinfered by gob walls as part of the process of remining for bottom hench. The roof in this locality is relatively strong, and in this respect quite different from Providence section, a
Rock	No. 13. Nos. 12, 29, 32, 43.	Depth, 332 feet; approached to about 100 feet from this school; inace cessible farther on account of old crush	371 acres mined. Depth, see sections on Plates 15, 17; thickness, s feet ginches: 3 inches refuse. This vein entirely closed and inacessible on account of squeeze. Reported to have forced Rock vein pillars down into openings in Big vein, and also affected portions of Diamond bed.a
Big.	No. 12. No. 29. No. 32. No. 43.	Depth about 145 feet; workings abandoned; openings large; pillars sound; many local falls of top coal in chambers; large pillars under school; could be easily flushed from hore hole. Squeezed here, pillars small for such a fluck hed. Depth, 348 feet; only top bench mined under school; and seam not bench, gracezed here, pillars small for such a fluck hed. Depth, 31 feet; thickness, 13 feet; hottom bench worked; local falls of top coal and rock under corner of school, but major part of building on large block of solid coal.  Depth, 325 feet; cuved and inaccessible.	367 acres mined. Depth, see sections on Plates 15 and 17; thickness, about 18 feet. First mining in either top or bottom beneck; then remined in places for remaining bench. This bet closed and inaccessible in many parts of mine, due to breaking down of roof. <sup>4</sup>
New County	No. 12. No. 13. No. 43. Nos. 32 and 29.	Depth, 160 feet; recently mined; endeavoring to columnize pillars Depth, about 360 feet, inacerssible on account falls.  Depth, 380 feet, worked from Bellevue; pillars usual size as per maps Not mined at present.	118 acros mined. Depth, see sections on Plates 15 and 17; thickness, about 1 to 8 feet, only about 10 feet below fig ven; pillars generally sound, but not columnized under Big vein; columnized under the vein; columnization attempted in recent mining.
a Surface subsidence may and often doc where many thick beds lie close together chambers or openings of an underlying bed	ence may and often eveds lie close togeth	a Surface subsidence may and often does occur where pillars are strong, and without much warning or crushing of pillars, if conditions exist such as those under Hyde Park, where many thick heds lie close together and the pillars in the several beds are not columnized, thus permitting pillars of an upper bed to break through the strata into the chambers or openings of an underlying bed.	shing of pillars, if conditions exist such as those under Hyde Park, mitting pillars of an upper bed to break through the strata into the

# Delaware, Lackawanna & Western Coal Co. collieries-Continued.

### BELLEVUE COLLIERY Continued.

Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Clark	No. 12. No. 29. No. 32. No. 48.	Depth, about 240 feet; nearly solid now; mined under north wall of 355 acres mined.  Depth, about 250 feet; nearly solid now; mined under north wall of 355 acres mined.  Depth, about 250 feet; not good.  Depth, about 250 feet; operations fair.  Depth, about 250 feet; operations fair.	335 acres mined. Depth, see sections on Plates 15 and 17; thickness 7 to 13 feet, with 1 to 2 feet of reduse; first mining in leaton benefit now remining for top benefit, in plates; pillars, generally standing and well distributed; old squeezed portions east of school No. 32, but gangways reopened; a conditions generally fair.
Dunmore No. 1		Not mined.	3 acres mined. Preparations now being made to work this bed.
Dunmore No. 2	XXX 00 XX 00	Depth, 350 feet; mined; condition good  Not mined. Depth, alout 500 feet; gangway under school; conditions good. Depth, 320 feet; workings in good condition; pillars sound and usual Depth, 600 feet; conditions good.	84 acres mined. Depth, see sections on Plates 15 and 47; thickness 5 to 6 feet; pillars usual size, and strong; conditions good throughout.
Dunmore No. 3		Not mined	38 acres mined. Opening in preparation for working this bed.
	1	CENTRAL COLLIERY. (Works Hyde Park section, South Main Avenue and Keyser Valley, south of Washburn Street.)	south of Washburn Street.)
Eight-foot		Eroded	Broded.
Five-foot		Part eroded	Partly erod d.
Four-foot		Part not mined	Balance not mined.
Diamond Rock		Worked from Hampton colliery (see page 26)	See page 26.
Big	. No. 32 Липех	Reported caved and inaccessible	362 acres mined. Depth, see sections on Plates 14, 15, and 16; thick-ness, 13 to 18 feet 2 to 3 feet refuse; this vein is generally closed by numerous local falls; pillars doubtless crushed or shattered in some places.
New County	do	Reported flushed and inaccessible	300 acres mined. Depth, see sections on Plates 14, 15, and 16; thickness, 9 to 10 feet, 2 feet refuse.a

Clark	do	Pillars sound, as shown on map; some local falls	370 acres mined. Depth. see sections on Plates 14, 15, and 16; thick-ness, 8 feet; 1 foot refuse.
Dunmore No. 1	do	Pillars sound; roof good; hard floor; recently mined; conditions good.  10 acres mined. Depth. see sections on Plates 14, 15, and 16; thick-recently mined; conditions good.  10 acres mined. Depth. see sections on Plates 14, 15, and 16; thick-recently mined—not be seen to be sections.	10 acres mined. Depth see sections on Plates 14, 15, and 16; thick- ness 4 feet. Il index coal and 3 feet. Il indo Feluer with bed— perhaps represents Dummore Nos. 1 and 2 united.
Dunmore Nos.2 and 3.		Not mined	Not mined.

# HYDE PARK COLLIERY AND CONTINENTAL COLLIERY

(Work Keyser Valley and Hyde Park section to South Main Avenue, between Lafayette Street and Luzerne Street.)

Eight-foot.		Broded	Eroded.
Five-foot	No. 31	Depth, 104 feet; mine just being opened; gangway working toward school, but under school not yet mined; conditions good.	2 acres mined. Depth, see sections on Plates 14 and 16; thickness, telet 8 inches clean coal. This bed extents under Hyde Park section generally, but until recently, normining has been done in it, now being developed from Hyde Park
	No. 19	Depth, about 140 feet; not yet mined	control y.
Four-foot	No. 31	Depth, about 144 feet; mine just being opened; gangway extending quite close to, but not now under the school; conditions good.	10 acres mined. Depth, see sections on Plates 14 and 16; thick-ness, 2 feet 10 incless, including 1 inch refuse. This bed extends under the Hyde Park section generally, but until receitly has not been mined; now being developed from
	No. 19:	Depth, about 175 feet; not mined	Hyde I'ark colliery.
Diamond	No. 31	Mined from Hampton (see p. 26)	355 acres mined. (See p. 26.)
Rock		Mined from Hampton (see p. 26)	240 acres mined. (See p. 26.)
Blg	No. 31	Depth, 374 feet; worked and caved; inaccessible Depth, 405 feet; inaccessible; mined and caved	514 acres mined. Depth, see sections on Plates 14 and 16; thickness, 13 to 18 feet; long mined; caved over large area and workings now abandoned.a
New County	No. 31. No. 19.	Depth 423 feet; pillars, regular and sound; no indications of settlement; old workings; good roof.  Depth, 440 feet; half of building on solid coal; remainder part mined; pillars fair size; roof and floor good.  Depth, 397 feet, mine openings filled with gob because of squeeze in progress in 1908; approached on gangway to 50 feet from school lot; all quiet now.	431 acres mined. Depth, see sections on Plates 14 to 16; thickness, 8 to 10 feet, includes 2 feet of refuse; workings in this bed look fair; workings accessible and pillars standing over large areas; no general squeeze; the caves or squeezes are local. Fillars in this and overlying beds are not columnized.

a Surface subsidence may and often does occur where pillars are strong, and without much warning or crushing of pillars, if conditions exist such as those under Hyde Park, where many thick seams it close depeter and the pillars in the several beds are not columnized; pillars of an upper bed are thus permitted to break through the intervening strata into the chambers of an underlying bed.

# Delaware, Lackawanna & Western Coal Co. collieries—Continued. HYDE PARK COLLIERY AND CONTINENTAL COLLIERY—Continued.

Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Clark	No. 31	Depth, 483 feet; roof, floor, pillars good; gangway, containing flush  Depth, 485 feet; roof, floor, part of lot; chambers under school flushed.  Depth, 485 feet; located over basin filled with water; not accessible.  Depth, 485 feet; located over basin filled with water; not accessible.	569 acres mined. Depth, see sections on Plates 14 and 16; thickness, 8 feet 8 inches, includes 2 feet refuse, pillars standing and workings in fair condition on major part of this section; now remining in some parts for bottom coal; this causes some chipping of pillars; some local fails and local squeezes.
Dunmore Nos. 1 No. 31	No. 31	Depth, about 529 feet; now opening these beeks not now mined under school, but gangway is approaching; pillars, roof, and floor all good.  So acres mined. Depth, see sections on Plates 14 and 16; thick-necks, No. 1 bed, 14 to 2 feet, dividing under this section in these beds and floor all good.  Not mined.	8 acres mined. Depth, see sections on Plates 14 and 16; thick-ness, No. 1 bed, 1½ to 2 feet; dividing rock, 8 feet; No. 2 bed, 34 feet. Mining under this section in these beds was recently begun and is now developing.
Dunmore No. 3		Not mined in this section	Not mined in this section.
		DIAMOND COLLIERY.	
	oW)	(Works North Hyde Park to Providence; river to Keyser Creek, between Pettebone Street and Court Street.)	Pettebone Street and ('ourt Street.)

Eight-foot		Eroded under schools	54 acres mined. Depth, see sections on Plate 12; thickness, 8 feet 8 inches, includes 1½-foot refuse. This bed present only under highest part of Hyde Park Hill and Brisbin, has been mined; reclaiming pillars now causing surface subsidence.
Five-foot	No. 30 No. 41	Depth, 51 feet; mined by Diamond drift Depth, 60 feet; mined, caved, and inaccessible under both schools	200 acres mined. Depth, see sections on Plate 12; thickness, 5 feet. This has been well mined over from Diamond drift; partly caved and abandoned.
Four-foot	No. 20.	Depth, 89 feet; on solid coal dividing Diamond drift workings and Brishin workings; over a fault; surrounding pillars fair, fair roof. Depth, 115 feet; disturbed by squeeze two years ago, now closed and inaceessible; approached to within about 60 feet of school.	42 acres mined. Depth, see sections on Plate 12; thickness, Twin bed 7 to 8 feet, including dividing rock 24 feet thick; this bed nearly closed, result of Diamond squeeze.
Diamond	No. 20 No. 21 No. 41	Depth, 255 feet; mined, closed, and inaccessible. Froded Depth, 242 feet; closed, caved, and inaccessible.	630 acres mined. Depth, see sections on Plate 12; thickness, 8 to 12 feet; mined from Diamond shaft; closed by falling roof and general squeeze; a now inaccessible.
Rock	No. 20 No. 41 No. 21	Depth, 234 feet. Depth, 272 feet; caved and inaccessible under both schools. On outcrop, not mined; too close to surface.	483 acres mined. Depth, see sections on Plate 12; thickness, 8 squeeze: nined from Diamond shaft; closed by general squeeze: now mining top split in Tripp shaft; hindered by 8 to 15 feet rock.

	1	RESEN	I CONI
499 acres mined. Depth, see sections on Plate 12; thickness, 10 to 13 feet; mined from Diamond shaft; closed by general squeeze, a	131 acres mined. Depth, see sections on Plate 12: thickness, 54 feet, includes it feet of refuse; this ven open and work.  Ing from Diamond shaft, room, 26 feet wride, 39 feet between centers, gob walls both sides of rooms, to dip from school No. 41 the workings are caved and inaccessible.	615 acres mined. Depth, see sections on Plate 12; thickness, $74$ teet, includes 8 inches refuse; largely mined over; disturbed by the general squeeze, and now full of water.	21 acres mined. Depth, see sections on Plate 12. These beds are 2 to 5 feet thick and are only being mined from Tripp shaft, but workings are of small extent.
Depth, 107 feet: map shows large pillar under school, but minework-   499 acres mined. Depth, see sections on Plate 12; thickness, 10 to inserved and inaccessible.  Depth, 345 feet: caved and inaccessible squeeze, a squeeze, a squeeze, a squeeze, a bepth, 331 feet; caved and inaccessible	Depth, 400 feet; not mined; nearest work 450 feet distant.  Depth, 101 feet; not mined.  Depth, 388 feet; we reached point in workings near school; chambers now being worked toward school; rooms, 26 feet; gob walls both sides.	Depth, 402 feet Depth, 400 feet inaccessible under both schools, on account squeezed see Manville value, area and water. See Manville colliery, page 32.	These seams not now mined under any school building,
No. 20. No. 41.	No. 20 No. 2 No. 41	No. 20. No. 41.	
Big	New County	Clark	Dunmore Nos. 1, 2, and 3.
(	97821°—Bu	11. 25—1	23

BRISBIN COLLIERY.

(Works under Keyser Valley and Hill section, between Hyde Park and Providence.)

The second secon	The second secon	The second secon
Eight-foot	No schools over Brisbin workings	24 acres mined. Depth, see sections on Plate 7; thickness, 8 feet 10 inches; mined out and robbed.
Five-foot.	op	130 acres mined. Depth, see sections on Plate 7; thickness, 8 feet 10 inches.
Four-foot	-do	123 acres mined. Depth, see sections on Plate 7; thickness 3 feet.
Diamond	do.	Worked from Diamond colliery. (See p. 30.)
Rock.	op.	$182~{\rm acres}$ mined. Depth, see sections on Plate 7; thickness, 3 feet 11 inches; mined out and caved.
Big.	op	289 acres mined. Depth, see sections on Plate 7; thickness, 10 feet 2 inches; caved and closed.
New County	ор.	00 acres mined. Too thin to mine, except on mountain side.
Clark.	op.	$404~{\rm acres}$ mined. Depth, see sections on Plate 7; thickness, 7 feet 7 inches; caved and closed.
Dunmore Nos. 1, 2, and 3.	op	4 acres mined. Now beginning to be opened.

a Surface subsidence may and often does occur where pillars are strong, and without much warning or crushing of pillars, if conditions exist as those under Hyde Park, where many thicks are locationary the pillars in the several beds are not columnized; pillars of an upper bed are thus permitted to break through the intervening strata into the chambers committed to break through the intervening strata into the chambers of an underlying bed.

# Delaware, Lackawanna & Western Coal Co. collicries-Continued.

# CAYUGA COLLIERY AND STORRS COLLIERY.

(Work section between Keyser Valley and Leggetts (Teek, from Bloom Avenue to foot of West Mountain.)

Section 1	V. Osmoo of control	Mining conditions under school month its.	General conditions.
Coal Deas.	Name of School.	MILLIE COUNTIONS CHICAL SOCIOL PARTIES	
Eight-foot		Eroded	Eroded.
Five-foot	No. 22	Depth, 36 feet; solid block coal under school.	208 acres mined. Depth, see sections on Plates 11 and 13; thickness, 4 feet 8 inches, includes 8 inches of refuse, pillars now being removed; space stowed with gob and surplus rock from a lower bed.
Four-foot	op	Depth, about 124 feet; mined, but inaccessible on account of danger  Jepth, about 124 feet; mined, but inaccessible on account of danger  Jepth, see sections on Plates Hand 13; thickness, det includes Sinches fallingroof, 25 feet thick, date to falling rook mining top split of Four-foot, 20 inches thick, and stowing surplus rock in Foot vein.	168 acres mined. Depth, see sections on Plates Hand 13; thickness, 4 feet, includes Sinchosof refuse, falling roof, 24 feet thick, closus the mine after standing; now mining top split of Four-foot, 20 inches thick, and stowing surplus rock in 5-foot vein.
Diamond	do	Depth, 186 feet; approached to 60 feet from school; pillars sound and of fair size; openings closed by falling roof; roof will not stand after timbers rot; pillars do not crush.	490 acres mined. Depth, see sections on Plates II and 13; thickness, S leet, includes 8 inches refuse; caved in many places; bad fire-clay roof which falls soon after working stops; pillars strong. <sup>a</sup>
Rock	do	Depth, 280 feet; pillars sound; rooms gobbed on one side; conditions good.	174 acres mined. Depth, see sections on Plates 11 and 13, thickness, 3 feet 3 inches clear, taking down 2½ feet of roof for height; roof good; conditions fair.
Big.	do	Depth, 317 feet; caved, closed, and inaccessible	623 acres mined. Depth, see sections on Plates 11 and 13; thickness, 10 feet, 1 foot 3 inches refuse; old mine caved and closed.
New County		Not mined; too thin	Not mined; too thin.
Clark	No. 23	Depth, 476 feet. This section of working flushed to within 2½ feet of roof, flushing still in progress.  Depth, 423 feet, mined but not accessible.	576 acres mined. Depth, see sections on Plates II and 13; thickness, 8 feet, includes 2 inches refuse; many local falls, but no general squeeze; workings now being flushed with culm.
Dunmore No. 1		Not mined.	Not mined, but now being opened.
Dunmore No. 2		do	Not mined; opening in preparation.
Dunmore No. 3			Do.

a Surface subsidence may and often does occur where pillars are strong, and without much warning or crushing of pillars, if conditions exist as those under Hyde Park, where many thick beds lie close together and the pillars in the several beds are not columnized; the pillars of an upper bed are thus permitted to break through the strata which separate the seams into the chambers or openings of an underlying bed.

### People's Coal Co.

## ONFORD COLLIERY.

(Works Hyde Park section, from the river to South Main Avenue, between Lackawanna and Luzerne Streets.)

Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Eight-foot		Eroded Not mined	Eroded. Not mined at present.
Diamond	No. 16.	Depth, 252 feet: approached to point under northwest corner of building: solid pillar under rest of school lot; bed, 10 feet thick: falls in room approaching school; conditions good. Depth, 200 feet; caved and inaccessible; approached to edge of coal worked by Bridge Coal Co.	84 acres mined. Depth, see sections on Plate 17: thickness, 10 to 15 feet, original workings in top bench, 3 to 6 feet, with about 24 feet refuse, vere acres eaved under No. 16 Section; pillars outside of cave apparently sound; a no indications of future caving, gob poes built under vicinity of Lackawanna Railroad Co.'s bridge and Lackawanna Avenue.
Rock.	No. 14 No. 16	Depth, 229 feet; inaccessible; worked from Hampton colliery Depth, 229 feet; caved and inaccessible; worked by Bridge Coal Co.	104 acres mined. Depth, see sections on Plate 17; thickness, 8 feet 2 inches, with 1 inch refuse; over 5 acres caved under No. 16 School, pillars sound surrounding cave, and no indications of spread of cave; a parts of Oxford working effectually flushed with culm.
Big	No. 14	Depth, about 364 feet: inaccessible, caved, and fushed.  Depth, 289 feet: inaccessible on aecount of cave: pillars surrounding cave appear in fair condition and usual size; a few local falls, but no indications of extension of caving: worked by Bridge Coal Co.	116 acres mined. Depth, see sections on Plate 17; thickness, 12 to 18 feet, with 2 to 3 feet of refuse; pillars and chambers of usual size; local falls, but no serious chipping or other indications of extension of cave, beyond 1 or 2 acres under Schoo INo. 16.4
New County	No. 14	See Hyde Park colliery, page 29.  Depth, about 334 feet; pillars standing in good condition and well distributed; no local falls; no present indication of settlement.	120 acres mined. Depth, see sections on Plate 17; thickness, 7 to 10 feet, with 1 to 2 feet of refuse; partly flushed: pillars standing, strong, roof good; no present indication of squeezing, a no caving under No. 16 School.
Clark	No. 16.	Depth, 435 feet; approached to within 250 feet of school; now inaccessible account local falls and flushing.  Depth, 370 feet: generally unwatered, and now accessible: pillars standing in good condition except for slight chipping; local falls in chamber under this school; old timber cogs standing, but bearing no weight; mined by Bridge Coal Co.	104 acres mined. Depth, see sections on Plate 17: thickness., 7 to 13 feet, about 2 feet refuse; openings large, but pillars firm, with fair distribution; slight chipping, but no present indications of subsidence.

a Surface subsidence may and often does occur where pillars are strong, and without much warning or crushing of pillars, if conditions exist such as those under Hyde Park, where many thick same is before and the pillars in the several beds are not columnized; pillars of an upper bed are thus permitted to break through the intervening strain into the chambers or openings of an underlying bed.

People's Coal Co. - Continued. OXFORD COLLIERY-Continued.

General conditions.	Depth, 516 feet; mined under northeast and southeast side, but and southeast side, but footh, 516 feet; mined under northeast and southeast side, but fact; not mined.  Tagic part solid; chambers well iffled with gob, and footh facts of the fact; not mined.  The fact is not mined.  The fact of rock, 24 feet of coal; rock and top bench taken down for height in roads; chambers, 30 feet; pillars, and footh facts in the pillars in the bunner.	Depth, 567 feet; heading and airway under central and eastern part of building over solid coal; recently mined; chambers well filled with gob.  Depth, 567 feet; heading and airway under central and eastern part of building over solid coal; recently mined; chambers well filled with gob.  The same of thickness, about and the filled with gob.  Columnized.	Depth, 620 feet; gangway and airway under central and eastern part of building; western corner on solid coal; recently mined. Depth, 568 feet; nined from westward only, up to line of school lot; not mined under the lot; mining stopped here.
Mining conditions under school properties.	Depth, 516 feet; mined under northeast and southeast side, but major part solid; chambers well iffled with gob, and mining stopped.  Depth, 481 feet; not mined.	Depth, 567 feet; heading and airway under central and eastern part of building over solid coal; recently mined; chambers well filled with gob.  Depth, 502 feet; not mined under school lot; mined from east side of the control of the coal; mined under school lot; mined from east side of the coal washward.	Depth, 620 feet; gangway and airway under central and eastern part of building; western corner on solid coal; recently mined. Depth, 518 feet; mined from westward only, up to line of school lot; not mined under the lot; mining stopped here.
Name of school.		No. 14.	No. 14
Coal beds.	Dunmore No. 1 No. 14	Dunmore No. 2	Dunmore No. 3

## Delaware & Hudson Canal Co. collicries.

## VON STORCH COLLIERY.

(Works Providence section, river to mountain, between Clearview and Putnam Streets, from river to Cayuga line, between Putnam and William.)

Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Eight-foot.	No. 24 No. 25	No schools.  Depth. 55 feet; pillars sound; conditions fair.  Depth, 37 feet; large pillar under entire school lot.	Worked and robbed.  104 acres mined. Depth, see sections on Plates 7 and 8; thickness, 4 fee 9 inches: 1 inch of refuse; firecaty roof, which falls; pillars well distributed and look good: rooms well packed with gob, inclusive of road ways when finished.
Four-foot	No. 24 No. 25	Depth, 147 feet; inaceessible; all openings filled with gob	165 acres mined. Depth, see sections on Plates 7 and 8; thickness 3 feet clear; chambers well filled with gob; many parts roadway also filled.
Diamond		Caved; abandoned; inaccessible.	365 acres mined. Depth, see sections on Plates 7 and 8; thickness, 10 to 15 feet includes 2 to 4 feet refuse. This hed carries 10 to 15 feet of falling freelay roof which soon disintegrates and falls, filling all openings.
Rock	No. 24 No. 25	Depth, 235 feet; solid, and too thin to mine here. Depth, 280 feet; caved and closed. Depth, 216 feet; solid under school lot; mined on west side only at present; violnity of School No.25 shows signs of squeeze.	395 acres mined. Depth. see sections on Plates 7 and 8; thickness, 3 feet 6 inches; 2 inches of refuse; falling roof; rooms filled with gob and falling roof.
Big.		(aved and closed	397 acres mined. Depth, see sections on Plates 7 and 8; thickness, 11 to 13 feet; closed throughout.
New County		Not mined; to date considered too thin to mine	6 acres mined.
Clark		Caved and closed	489 acres mined. Depth, see sections on Plates 7 and 8; thickness, 7 to 9 feet; caved and closed throughout.
Dunmore beds		These beds mined by West Ridge colliery (see p. 23). No. 40 School undermined from this colliery in Diamond, Big, and Clark beds, but workings are caved and closed.	

# Delaware & Hudson Canal Co. collieries-Continued.

## LEGGETTS CREEK COLLIERY.

(Works north Providence section, bounded by East Market Street, North Main Avenue, and the city line.)

		The state of the s	and avenue, that the call time.)
Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Eight-foot		Broded	Eroded.
Pave-foot	No. 41. No. 26.	Worked out and abandoned. Froded,	33 acres mined. Depth, see sections on Plates 10 and 11; thickness, 3 feet 6 incluse to 5 feet, worked out and abandoned.
Four-foot	No. 26.	Depth, 65 feet; inaccessible; filled with rock or gangway fallen	263 acres mined. Depth, see sections on Plates 10 and 11; thickness, 3 feet 6 inches; chambers well filled with gob.
Dlamond	No. 24. No. 26. No. 44.	Depth, 212 feet; caved, closed, and abandoned. Depth, E35 feet; caved, closed and abandoned. Caved, closed, and abandoned.	28 acres mined. Depth, see sections on Plates 10 and 11; thickness, 8 feet to 10 feet; carries to to 15 feet of falling roof of firreday and shale which has fallen and closed all openings through-
Rock	No. 24. No. 26. No. 4f.	Depth, 235 feet; not yet mined. Depth, 172 feet; rooms filled with gob both sides of roadway; pillars sound; roof strong. Now extended under school; cob walls both sides; no signs at present of squeeze in Dummore bed; conditions fair.	out.  98 acresmined. Depth, see sections on Plates 16 and 11; thickness, 24 to 3 feet; rooms well filled with gob on both sides; conditions fair.
Big.		This bed flushed under School No. 25 and eaved and closed under Nos. 24, 25, and 44, west half of School No. 25 is over solid pillar in all veins.	355 acres mined. Depth, see sections on Plates 10 and 11; thickness, 11 to 12 feet; mined and abandoned long ago; now caved and closed.
New County		Too thin to mine	Not mined; too thin.
Dunmore No. 1	No. 26.	This bed reported closed under all schools. See Dickson colliery, page 38. Not mined; too thin	296 acres mined. Depth, see sections on Plates 10 and 11; thickness, Seet; mined, abandoned, and dosed.  Not mined, too thin. Bottom split of Dunmore No. 1 is here known as Dunmore No. 2.
Dunmore No. 2	No. 26 No. 44	Depth, 531 feet; very thin; not worked 2½ feet thick; rooms filled with gob.	51 acros mined. Dopth, see sections on Plates 10 and 11: thickness, 1 to 2 feet; only small area mined where thicknest. This bed at this colliery is known as No. 3.
Dunmore No.3(here known as No. 4).	No. 25.	Depth, 670 feet; pillars sound; roof sound; rooms stowed with rock; 333 acres mined. Depth, see sections on Plates 10 and 11; thickness, contificus hir, all performed to the control of section of seed of the control of seed of seed of the control of seed of the control of seed of s	333 acres mined. Depth, see sections on Plates toand 11; thickness, feet, with about 1 food of reduce on top; rooms fair, all goldbed with rock; pillars not sufficiently large or strong to sustain pressure of roof, consequently squeezing is in
	No. 26.	Depth 573 feet; no signs of squeeze here at present; flush pipe laid from You Storfed breaker to flush this locality, which, judg-floged by squeeze and inaccessible.	progress, 700, part and Strong, which remains thrace after squeeze. This bed is here known as No. 4 Dumnore.

## MARVINE COLLIERY.

# (Works between Providence and the city line, from Florida Street to Dunmore and Olyphant Road.)

Eight-foot	14 OX	Eroded.  Near surface: worked out and alendoned years ago.	Eroded. 150 gares mined. Depth see sections on Plates 0 and 10: thickness.
Four-foot		Operated from Leggetts Creek colliery (see p. 36)	See page 36.
Diamond	No. 44.	See Leggetts Creek colliery, page 36	135 acres mined. Depth, see sections on Plates S and 10; thickness, 9 to 10 feet; bad falling fireclay roof, now being mined under Marvine farm on east side of mine; on west side now reopening caved area caused by recent general squeeze.
Rock	do	See Leggetts Creek colliery, page 36	This vein not mined at Marvine colliery.
Big.	do	Mined, abandoned, and caved	445 acresmined. Depth, seesections on Plates 9 and 10; thiekness, 13 to 14 feet, divides into two splits on east side, where it is now being worked under Marvine farm where there are few surface improvements.
New County		Not mined; too thin.	Too thin to mine.
Clark	No. 44	. Worked from Leggetts ('reek colliery (see p. 36)	242 acres mined. Depth, see sections on Plates 9 and 10; thickness, 5 to 6 feet, largely caved and closed on west side; open and partly mined on east side; few improvements on surface east side.
Dunmore No. 1	do	See Leggetts Creek colliery, page 36.	Too thin to mine.
Dunmore No. 2			$53~\rm acres~mined.$ Depth, see sections on Plates 9 and $10;$ thickness. $2\pm to~3~\rm feet,$ not much mined as yet.
Dunmore No. 3		No schools over the Marvine workings	74 acres mined. Depth, see sections on Plates 9 and 10; thickness, 44 feet, includes 1 foot of refuse. These workings have enforced in the sections.
		•	squeeze has more or less affected overlying beds and has extended to Leggetts Creek mine, now working under good conditions on east side under Marvine farm.

# Delaware & Hudson Canal Co. collicries-Continued.

## DICKSON COLLIERY.

(Works Green Ridge section from the river to the Dunmore line and from Delaware Street to Columbia Avenue.)

General conditions.	Broded.  101 acres mined. Depth, see sections on Plates 6 and 8; thickness 12 feet; includes 2 feet 4 inches of reluse, workings stopped account thin cover of sand and gravel; standing philars fair.	194 acres mined. Depth, see sections on Plates 6 to 8; thickness of 8 feet includes 9 inches of refuse; pillars standing in fair condition; local falls, but no squeeze as yet.	83 acres mined. Depth, see sections on Plates 6 and 8; thickness, pillars sound; conditions fair. This is bottom split of the bed and is here known as Dunmore No. 2, top split being called No. 1.	50 acres mined. Depth, see sections on Plates 6 and 8; bed rather thin, and therefore not extensively mined; where mined, rooms filled and conditions fair; here known as Dunnore No. 3.	351 acres mined. Depth, see sections on Plates 6 and 8: thickness, 3 to 3½ feet; well mined over; pillars generally sound; rooms well filled with gob; conditions fair.
Mining conditions under school properties.	Eroded.  Broded.  Just over the line on Pennsylvania Coal Co. land and not undermined.  Just over the line on Pennsylvania Coal Co. land and not undermined.  Just over the line on Pennsylvania Coal Co. land and not undermined.  Just over the line of sand and gravel; standing pillars arount thin cover of sand and gravel; standing pillars fair.	Contains too much refuse to mine at present. About 5 feet thick  Depth, 226 feet; this school on Pennsylvania Coal Co. land, near  Sfeet includes 9 inches of refuse; pilars standing in fair condition; local falls, but no squeeze as yet.	Depth, 289 feet; near to land line on Pennsylvania Coal Co. land; 83 acres mined. Depth, see sections on Plates 6 and 8; thickness, not mined.  2 feet 2 inches; well mined over; rooms well gobbed, pillars sound; conditions fair. This is bottom split of the bed and is here known as Dunnore No. 2, top split being called No. 1.	Just over line on Pennsylvania Coal Co. land; not mined	Depth, 384 feet; just over line on Pennsylvania Coal Co. land; not 351 acres mined. Depth, see sections on Plates 6 and 8; thickness, mined.  351 acres mined. Depth, see sections on Plates 6 and 8; thickness, 3 to 34 feet; well mined over; pillars generally sound; rooms well filled with gob; conditions fair.
Name of school.	No. 27	No. 27.		do	do.
Coal beds.	All beds above Big.	New County	Dunmore No. 1	Dunmore No. 2	Dunmore No. 3

# Manville collicty-Operated jointly by the Delaware, Lackawanna & Western and Delaware & Hudson Companies.

(Works Green Ridge section, from the river to the Dunmore line, between Larch and Delaware Streets.)

Name of school. Mining conditions under school properties.	the Eroded.	No. 21. Worked by Diamond colliery. (See p. 31) Eroded, except small area on west side of river; worked by Diamond colliery and 34. Eroded.	No. 21 Depth, about 160 feet; not mined; workings not extended under 16 acres mined. Depth, see sections on Plates 5 and 6: thickness, school.  No. 28 Depth, about 160 feet in or mined.  No. 34 Depth, about 170 feet; not mined.  Solid by 8 to 10 feet of rock; mining only recently begun; chambers, 24 feet; pillars, 36 feet.	No. 21. Depth, about 261 feet: inaccessible on account of water.  No. 28. Depth, about 290 feet.  No. 28. Depth, about 290 feet.  No. 28. Depth, about 290 feet.  No. 28. Teet, with 5 inches of refuse of refuse of refuse of refuse.  No. 28. Teet, with 6 inches of refuse of refuse.  No. 28. Teet, with 6 inches of refuse of refuse.  No. 28. Teet, with 6 inches of refuse.  No. 28. Teet, with 6 inches of dear of the mine is now caved and closed.  Solution and closed.	here Not mined. Not mined.	1 No. 21 Depth, about 325 feet; pillars sound and as shown; rooms filled with pepth, 227 feet; pillars sound and as represented; rooms filled with pepth, 227 feet; pillars sound and as represented; rooms filled with pepth, 227 feet; pillars sound and as represented; rooms filled with pepth, 227 feet; pillars sound and as represented; rooms filled with pepth, 227 feet; pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth, 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and as represented; rooms filled with pepth 227 feet pillars sound and pepth 227 feet pillars sound and pepth 227 feet pillars sound and pepth 227 feet pillars sound a	No. 21 Depth, about 365 feet; pillars sound and well distributed; rooms full of gob, except roadway in center; openings large; conditions fair.  No. 34 Depth, 387 feet; pillars sound and rooms full of gob, except roadway.  No. 28 Depth, 285 feet; workings inaccessible; reported filled and settled.  No. 28 Depth, about 365 feet; pillars sound and rooms full of gob, except roadway of squeeze fullers well distributed, hat squeezed; area reported failed and settled.  No. 28 Depth, see sections on Plates 5 and 6: thickness;	No. 21. Depth, 447 feet; pillars sound and according to maps; rooms filled with a solutions fair.  No. 34. Depth, 56 etc.; pillars sound and as represented; rooms filled with a solution fair.  No. 24. No. 25. Depth, 56 etc.; pillars sound and as represented; rooms filled with a solution fair.  No. 26. No. 27. Depth, 447 feet; pillars sound and as represented; rooms filled with poly, excepting readway; conditions fair.  No. 28. This best pillars sound and as shown on maps; rooms rooms filled with poly, except roadway; conditions fair.  No. 29. This best pillars sound and as shown on maps; rooms rooms filled with poly, except roadway; conditions fair.
Name of s		No. 21. Nos. 28 and	No. 21	N.0. 34 N.0. 34 N.0. 98		No. 21		
Coal beds.	All beds above the Big vein.	Big	New County	Clark	Top Split (here known as Dummore No. 1).	Dunmore No. 1 (here known as No. 2).	Dunmore No. 2 (here known as No. 3).	Dunmore No. 3 (here known as No. 4).

## Pennsylvania Coal Co. collicry.

## NO. 2 SHAFT COLLIERY.

(Works Petersburg section, between Myrtle Street and Dunmore, east of Taylor Avenue.)

Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Bods above the Clark.		All erockell	Lacre mined. All beds above the Clark are eroded.
Clark	No. 5	Depth, 30 feet; pillars standing firm and sound; no falls; good roof 20 acres mined. Depth, see sections on Plates 4 and 24; thickness, feet; 1 foot bottom lifted in rounds; company now reopening, of post old mine; pillars strong; company now reopening, preparing to flush with culm and rectain pillars.	20 acres mined. Depth, see sections on Plates 4 and 24; thickness, 5 feet, 1 foot bottom lifted in reads cleanbors encesixth full of gods, old mine, pillars strong, company new reopening, preparing to flush with culm and reclaim pillars.
Dummore No. 1	do	Depth, 170 feet; pillars strong and well distributed; no signs of weak- and a freq. 10 inches clear coal; pillars sound, well distributed, and strong; no signs of weakness; top beneh 3! feet thick, and strong; no signs of weakness; top beneh 3! feet thick, feet above bed; company now remining near outcrop for top coal.	105 acres mined. Depth, see sections on Plates 4 and 24, thickness, 4 feet 10 inches clear coal; pilars sound, well distributed, and strong, no signs of weakness; top beneh 34 feet thick, 3 feet alove bed; company now remining near outerop for top coal.
Dummore No. 2	do	Depth, 200 feet; pillars strong; roof excellent; condition good	73 acres mined. Depth, see sections on Plates 4 and 24; thickness, 5 for 1 medes; 3 inches of refuse; pilars strong and well distributed; no signs of weakness; pillars near outcrop being reclaimed.
Dunmore No. 3	do	Depth, 250 feet; not mined	16 acres mined. Depth, see sections on Plates 4 and 24; thickness about 3 to 4 feet, not much mined.

## Green Ridge Coal Co.

## GREEN RIDGE COLLIERY.

(Works small area in city between Ash and Poplar Streets and between Monroe and Taylor Avenues.)

8,					
	General conditions.	Formerly mined and caved; thirekness, 8 feet; now being mined to recover pillars; openings being well filled with gob and surplus new from lower bods; surface now settling somewhat in parts of this area; depth, about 175 feet. esset sections on Pl. 4.)	Depth, 248 feet (see sections on Pt. 4); thickness, 4 feet, mined crewed, and squeezed wents ago; roof resting on old gobs; now being routined to win top eeal formerly refe; open fines long fillied, and surplus rook stowed in fark level This upper splif of No. 1 Dunmore is known at Mancille and Dicksonas No. I, and bottom benchas No. 2 Dunmore.	Depth, 271 feet (see sections on Pt. 4); thickness, about 5 feet; known here as Dumore No. 3; this bed mined and caved, and inaccessible under city.	Mined and caved under city; now inaceossible; depth, 303 feet (see sections on Pl. 4); thickness, 3 to 4 leet.
	Mining conditions under school properties.	No schools over these workings.		No schools over this bed	
	Name of school.				
	Coal beds.	Clark	Dumnore No. 1	Pummore No. 2	Punmore No. 3, China vein.

## North End Coal Co. colliery. NORTH END COLLIERY.

(Works the upper beds near Leggetts Gap.)

Coal beds.	Name of school.	Mining conditions under school properties.	General conditions.
Beds above Dia-		Eroded	Broded.
Diamond No. 23.	No. 23.	op-	Company remining old workings; now being worked along outcrop on steep dip and under mountain side, where few improvements exist on surface.
Rock	do	Outcrops under school; pitch, 45°; thickness, 3 to 4 feet; pillars, good size; conditions fair at present, but pillars should not be disturbed.	Company remining old workings (see sections on Pls, 11 and 13); thickness, 32 feet; divided bed in eastern part; top bench, 3 feet rock, 3 feet; bottom bench, 3 feet 2 inches; dip of bed about 45°, crop falls hable on surface If upper pillars are removed.
Blg.	.do.	Fitch, 45°; bed outcrops about 100 feet north of corner of building; under center of building its about 135 feet deep to boutom of bed; thickness, 18 feet or more, openings large, and should be filled; south side of school lot now protected by large pillar only partly under school lot; to southwardliff is, down pich from this large pillar—is immense excavation 24 feet high by nearly 90 feet square, only about one-sixth filled with falling rock and coal that has slid of from pillar.	Company remining old workings; thickness, 15 to 25 feet; dip, 45°; openings large; large crop caves liable to occur if pillars are removed.
New County	do	Depth, 275 to 336 feet; pitch, 50°; lowest workings are north of company remining old workings (see sections on Pls. 11 and 13); school; thickness, 1½ feet; not mined under school.	Company remining old workings (see sections on Pis. 11 and 13); bed very thin; only mined near outcrop.
Beds below New County.		See Cayuga colliery, page 32.	Not mined by North End colliery except in mountain side near outcrop.

Clearriew Coal Co. collicry.

Works South Providence north of Clearview Street, strip 200 feet wide, from North Main Avenue to Keyser Valley Branch of Delaware, Lackawanna & Western Railroad.)

This colliery is now engaged at second mining in the two top beds under above locality. These openings are expected to extend eventually under School No. 40, but will not reach this point for several years. The operation is small, and the output is delivered by wagons.

## Bull's Head Coal Co.

(Works near junction of North Main Avenue with Providence Road.)

This colliery is engaged at second mining of the Diamond and the top split of the Four-Foot beds under Winton, Church, and Nassau tracts in above locality. No school improvements on these lands. Operation for local consumption, and delivery by wagon.

## Mountain Lake Coal Co.

(Works on mountain side near Mountain Lake, east of Laurel line.)

This mine works an island of coal in Dunmore bed on mountain east of Laurel line, for local consumption; delivery by wagon. No surface improvements over the coal bed.

### OBSERVATIONS ON PRESENT MINING CONDITIONS UNDER SCRANTON.

### INTRODUCTORY STATEMENT.

As stated in the chapter on the history of anthracite, the mining methods pursued in the earlier days of the industry, not only in Scranton, but everywhere in the anthracite fields, were not conducted with the view of ultimately mining the maximum amount of coal, with the least effect upon the surface, but with a view to immediate profits. Hence, little attention was given to surveying and engineering in the early mines, and great irregularity in the method of mining was the rule rather than the exception. This irregularity makes it exceedingly difficult to columnize pillars now where mining is being done in the solid under worked-over portions of higher coal beds.

To illustrate this particular point reference is made to the tracings that show the mine workings under the various school properties and are in the possession of the board of school control. These tracings are included in the report made by Messrs. Stevenson and Knight. In the more recent mining under the city, the attempt has been made to remedy this defect, and this attempt has been fairly successful.

As the result of our inspection of the mines under Scranton, as given in detail on preceding pages, we have grouped the mine workings into several classes; in each of these classes approximately similar conditions obtain, and to each the same remedies for sustaining the surface might apply, as stated below:

### SURFACE BEDS.

### WEST SIDE OF LACKAWANNA RIVER.

On the west side of the Lackawanna River, at the Dodge, Hyde Park, Mt. Pleasant, Diamond, Brisbin, Cayuga, Von Storch, and Leggetts Creek collieries, the surface beds being mined are known as the Eight-foot, Five-foot, and two splits of the Four-foot.

As before stated there is only a small area underlain by the Eightfoot; the areas underlain by the other beds gradually increase in size, as the beds are lower in the measures.

In mining these beds efforts have been made—with a fair degree of success—to columnize the pillars, and about the usual percentage of coal, approximately 33\(\frac{1}{3}\) per cent on first mining, is left in for support of the overburden. In a few places reclamation of pillars, or what is commonly termed "robbing," is in progress, but only where there are comparatively few surface improvements. The menace to the surface from the mining of these beds, as at present conducted, is comparatively slight. When the time comes, however, for the reclamation of pillars from the greater part of the area mentioned, serious surface disturbance may be expected, unless in the meantime some method of support is introduced. Suggestions on this point are given on subsequent pages.

### SOUTH AND EAST SIDES OF THE LACKAWANNA RIVER.

On the south and east sides of the Lackawanna River, at the National mine, the Big and the New County beds are nearest the surface under a part of the property, the Clark vein under another part, and the Dunmore No. 2 under still another part. The part underlain by the New County and Big beds carries few improvements and is much caved, so that no serious result is likely to occur by reason of the extraction of the remaining pillars. The mined-over part of the Clark bed, as will be noted from the plans, underlies a larger area than the mined-over part of either of the two overlying beds; and before extraction of pillars from the Clark bed is begun, measures for the support of the overburden should be adopted where the surface improvements are of sufficient value to justify the expense. This observation refers particularly to the part of the bed formerly worked from the old Meadow Brook mine; it underlies a thickly settled portion of the south side.

As will be noted on Plates 19, 20, and 21 the Dunmore No. 2 is the surface bed over a considerable portion of the National and Meadow Brook operations, extending from Beech Street to Sanders Street, and from the Erie & Wyoming Valley Railroad to the Lackawanna River. Examination of workings in this bed, and inspection of the mine maps, indicate that considerably less than the usual one-third has been left in pillars for support. There is no mining now in progress in this bed, nor any extraction of pillars. The pillars observed under the area mentioned (particularly between Beech and Breck Streets), and between Pittston Avenue and Crown Avenue, show signs of pressure and should not be disturbed. Although it is true that these pillars have stood without serious subsidence for many years, there is a possibility of a "creep" or "squeeze," such as would unquestionably cause surface damage in the area just mentioned, starting at almost any time. Remedial measures should be applied in the Dunmore No. 2 bed in this area at the earliest possible moment, before a creep or squeeze starts, as the conditions are such that if once started, no remedies that might be attempted, and hastily applied, would be effective in preventing a general subsidence of practically all the above mentioned area.

### CENTRAL PART OF SCRANTON.

The Pine Brook colliery of the Scranton Coal Co. includes a large area in the central part of the city of Scranton, as will be noted from Plates Nos. 1, 2, 3, 4, 5, and 22. This area extends eastward from Beech Street on the south side to Poplar Street at the Dunmore line, and from the Lackawanna River to the outcrop of the Dunmore beds near Nay Aug Park.

Under a portion of the territory mentioned, the Big or Fourteen-foot bed is present. It was partly worked over many years ago by the old Lackawanna Iron & Coal Co. The area underlain by this bed is what is generally known as Sanderson Hill, and is clearly shown in Plates Nos. 2, 3, and 4. The old workings in the Big bed are inaccessible, except a very small portion that extends from the Pine Brook Traveling Way to a point under the Central High School. Although there may be other openings to the workings in this bed, they are unknown to us. From information furnished by various persons, it is believed that the old maps of the workings in this bed are reasonably accurate.

The part of these workings that was inspected showed the pillars in good condition and the roof over the openings fairly sound, although local falls have occurred in many openings preventing access to points beyond. According to our information no serious "creeps" or "squeezes" have occurred in this bed, and unless some disturbance takes place through subsidence of the measures below it not much danger is to be apprehended from a general creep in this bed. We are, however, of the opinion that detailed investigations should be made by reopening small holes through the local falls mentioned above, and by sinking shallow shafts at various points for the purpose of making accurate surveys of the mine workings. These should be maintained as avenues through which to conduct or transport material for filling. It is deemed especially important that these openings be completely filled, on account of the nearness of this bed to the surface, and the value of the surface improvements. Methods of protection will be described in another chapter.

Below the Big bed the next bed that has been worked from the Pine Brook shaft is the Clark. The New County bed has not been worked at Pine Brook, but it is present and will doubtless be mined in the future. The Pine Brook workings include what was formerly the property of the Fair Lawn Coal Co., between Gibson and Ash Streets, and Capouse and Quincy Avenues. The usual rule of leaving approximately one-third of the coal was generally followed in the major part of the workings from the Pine Brook shaft, but much less than one-third was left in the Clark bed where worked from Fair Lawn. This bed is from 8 to 11 feet thick; a bench of coal at about the middle of the bed that is considerably softer than the balance was noted. This bench is affected by what is known as "air slack," causing it to chip and flake off, and to show the first signs of any undue pressure on the pillars.

A very large proportion of the pillars inspected an this bed show unmistakable signs of pressure, particularly in the Fair Lawn workings and outwardly from this area for a considerable distance. These signs of pressure on the pillars can not, in our opinion, be solely attributed to air slack, but are, we believe, the first stage of a creep or squeeze that if fully started may result in the complete collapse of the pillars in a large part of the area mentioned; it would bring down the roof, and unquestionably affect the surface. These indications, as before stated, are most serious in the Fair Lawn workings; they are observed on both sides of the tract and under the portion of the property where the Big Vein is present. Should a general squeeze take place in the Clark bed workings it would certainly affect the pillars and overlying strata of the Big bed and result in a very serious disturbance of the surface.

We deem it important to lay particular stress on the necessity for promptly taking measures to prevent the *starting* of a general squeeze or creep in the Clark bed at the Pine Brook colliery; for such a squeeze might cause breakages of gas, water and sewer mains, and resultant damages.

A point of particular weakness in this bed is under the Technical High School, near the intersection of Adams Avenue and Gibson Street. We have been informed that the Scranton Coal Co. has begun flushing culm into the workings under this important building, and that it is their intention to fill these workings as rapidly as possible. When this flushing is completed and a block of 1 or 2 acres is completely flushed, it will strengthen not only the point immediately filled, but have a tendency to support the roof for some distance on all sides of the artificial pillar thus introduced.

The old Lackawanna Iron & Coal Co. opened and worked the Clark bed by a drift from Roaring Brook gorge, near the Laurel line station. These old workings are now inaccessible, but maps inspected show an area worked over on the north and east sides of the river bank between the Delaware, Lackawanna & Western Railroad and Vine Street, and Madison and Clay Avenues. The maps show that very small pillars were left in. The old workings should be opened and artificial pillars made by flushing. The same plan is suggested for the Big, or Fourteen-foot, bed under Sanderson Hill, and for the old Iron Co. workings in this bed on the south side of Roaring Brook, under Spruk's lumber yard and vicinity.

At the Manville colliery, operated jointly by the Delaware, Lackawanna & Western and the Delaware & Hudson Companies, the surface bed is the New County. This bed has been attacked recently, and is now being mined under the Green Ridge section of the city. It averages about 6 feet thick, with nearly 2 feet of refuse in several benches. We were informed that under the old leases the lessees were prohibited from mining this bed, but by a recent modification of the terms of certain of the leases they are permitted to extract one-third of the bed, leaving two-thirds as pillars to support the overburden. Considering the depth at which the bed lies and the char-

acter of the overlying strata, we do not think there is much danger to the surface from mining this bed, if not more than one-third of the coal is extracted.

At this colliery the Clark bed has been worked over the whole of the area tributary to the mine, as will be noted from Plates 5, 6, and 7, and is at present abandoned, no solid or pillar mining being in progress. About the usual one-third of the coal has been left to support the roof. Many parts of these workings are inaccessible because of local falls, and a small part of the workings has been filled with culm, principally under surface improvements controlled by the

mining company.

The pillars in this bed show the usual chipping, due to air slack, and in some places signs of squeeze or creep, particularly in the vicinity of Poplar Street and between Capouse and Washington Avenues. The boundary pillar between the Manville workings and those of the Pine Brook mine is very small, and would not be of sufficient strength, in our opinion, to break off or stop a squeeze that might originate on either side of it. We are of the opinion, therefore, that filling or other remedial measures for the support of the overburden should be started in portions of the Manville Clark-bed workings, as we recommended at Pine Brook.

At the Dickson mine of the Delaware & Hudson Co. the surface bed is the Big, or Fourteen-foot, which is 10 to 14 feet thick. This bed was worked some years ago between the river and Dickson Avenue and between Delaware and Market Streets; a very small part east of Sanderson Avenue was also worked.

No mining, either of solid coal or pillars is now being done in this bed. There is, however, a considerable block of solid coal east of Sanderson Avenue that may at some time be extracted. If mining is resumed in this bed it should be conducted with great care, as the bed is close to the surface, and the overlying strata are weak.

Parts of this bed west of the Delaware & Hudson Railroad and under the Lackawanna River have been flushed with culm, and the balance of the workings should be filled in the same manner. The possibility of recovering the pillars in the worked-over part of this bed without serious damage to the surface is, in our opinion, decidedly doubtful, even though the openings may be completely filled with culm or other flushed-in material.

The New County bed has not been worked at the Dickson mine, being considered too thin and impure for profitable extraction. This bed, however, may be mined hereafter.

The Clark bed has been mined in about the same manner as at Pine Brook and Manville, and the same remarks regarding conditions apply. Portions of this bed also have been filled with culm, particularly toward the Lackawanna River.

### MIDDLE BEDS.

### HYDE PARK AND PROVIDENCE SECTIONS.

As before mentioned, under Hyde Park and Providence, the middle series of beds, the Diamond, Rock, Big, New County, and Clark (especially the first three of these), are quite thick and the intervening strata are comparatively thin and weak. On account of the failure in the past to columnize pillars, the workings in these beds, where now open, constitute a serious menace to the surface, and this portion of the city will be the most expensive and difficult to protect. However, it should be noted that very large areas of the three uppermost beds have been closed by crushing of the pillars and strata in the past. This condition was observed in parts of the Bellevue, Hyde Park, Hampton, Oxford, Mount Pleasant, Diamond, Brisbin, Cayuga, Von Storch, Leggetts Creek, and Marvine mines. Where such complete crushing of the pillars, with consequent subsidence of the overlying strata and surface, has taken place in the past, no serious apprehensions need be entertained of future damage to the surface improvements, unless, in the process of mining lower veins, insufficient pillar support is left to carry the overburden and a creep or squeeze takes place. This has been the case recently at the Leggetts Creek mine in mining the lower Dunmore bed at a depth of 700 feet, where was applied the usual though here insufficient rule of leaving about one-third of the coal for support.

Where the workings in these thick and closely lying beds are not closed by a general crush (and no one knows how large or extensive such openings may be) there is always a liability to a repetition of the same kind of subsidence as that which wrecked No. 16 School. In this connection attention is particularly called to the conditions existing under No. 12 School. Here the Diamond bed is very near the surface, within 13 to 40 feet. Second mining is now in progress to win bottom coal formerly left in this bed, and the New County bed is being mined. An attempt is being made to drive openings in the New County bed under openings in the Big bed, but this attempt is not altogether successful. These conditions, we believe, are quite similar to those formerly existing under No. 16 School.

We strongly recommend that the pillars in the Diamond, Rock, Big, and New County beds under this building should not be disturbed, and that the openings in the Diamond, Rock, and Big beds should be filled as promptly as possible. Such filling could easily be done by drilling one or two bore holes in the school lot. The filling of openings should not be confined to the school lot only, but should extend outside the lot some distance, as there is danger in case of a cave in any seam, of the side pull damaging the building.

It is also deemed important to refer particularly to No. 23 School, where the Rock and the Big bed pillars now in place should not under any circumstances be disturbed, neither under the school lot nor for some distance outside of it, as shown by the maps formerly submitted to the school board by the North End Coal Co. We also suggest that the openings under this school property should be flushed full of sand, culm, or other material.

The best manner of applying an effective remedy for this serious menace is difficult to determine, because the openings are so large, on account of the thickness of the seams, and there is the difficulty of procuring the material for this purpose.

### DUNMORE BEDS.

The deeper-lying Dunmore beds under the major portion of the city, constitute a class by themselves. They are in many places so thin that during mining much top or bottom rock has been removed in all the gangways and along roads in the chambers to make room for cars and mules. This rock with the large quantity of interstratified refuse that is usually present in the coal beds nearly fills the minedout space when stowed in the chambers, and thus constitutes a check to quick or total subsidence. Then, too, the thickness of the rock over the coal is generally so great that local caves in the workings are not likely to affect the surface. The greatest menace to the surface property from these deep thin beds is through a general subsidence—a creep or squeeze extending over large areas. Even then the settlement will be gradual, and as a rule so uniform as to cause little or no damage to surface property, except where the uniformity of the subsidence is interrupted or prevented by the presence of very large pillars or solid blocks of unmined coal, in which event, buildings located on the surface over or near the margin of such large pillars will be liable to considerable damage by the side pull, or uneven subsidence.

In consequence of these facts we would advise as a measure of preventing damage to surface improvements over these deeper beds that the Dunmore beds be mined in the usual manner under large blocks of coal now held as reservations in any of the coal beds overlying the Dunmore and not at present mined nor intended to be mined.

### RECAPITULATION.

Thus, to recapitulate, we have three general sets of conditions which naturally divide the coal workings into as many separate classes, to wit:

1. The surface beds, viz, on the west side, the Eight-foot, Five-foot, and Four-foot; on the east side, the Big, New County, Clark, and Dunmore No. 2, of which the latter are surface beds under different parts of the south side and central city sections.

- 2. The middle series of beds, viz, Diamond, Rock, Big, New County, and Clark, under the Hyde Park and Providence sections.
- 3. The three lowest beds, Dunmore No. 1, Dunmore No. 2, and Dunmore No. 3, under the major part of the city.

### METHODS FOR SURFACE SUPPORT.

The methods employed at the present time for supporting the surface over the coal mines under the city of Scranton are of two general classes, which may be termed natural and artificial.

### NATURAL OR PILLAR SUPPORT.

The natural method, of course, consists in leaving pillars of coal sufficiently strong to support the weight of the earth and rock that overlie the coal bed. The efficiency and value of these supports depend upon their size. That is, the horizontal area, the height of the pillar (which is fixed by the thickness of the coal bed), the compressive strength of the coal, the regularity of distribution of the pillars, and whether or not they are columnized with respect to pillars in near-by overlying or underlying beds, all have to be considered. In this vicinity the size of pillars has been mainly regulated by the one-third rule previously mentioned.

### ARTIFICIAL SUPPORT.

### FLUSHING.

There are several artificial methods of roof support, the principal and most effective of which is known as the flushing method. In this method coal culm and other fine refuse is washed into the mines through pipes by means of a stream of water, thus filling the desired portions of the mine.

This method was first used at Shenandoah, Pa., by the Philadelphia & Reading Coal & Iron Co. Afterwards it was introduced at Plymouth, Pa., and now has been adopted and is in practice over the whole anthracite region. Only culm is used, and the method has been adopted mainly for the purpose of protecting those parts of the mine or of the surface which it is necessary to support in order to maintain the mining operations.

Under Scranton considerable flushing has been done at various places, as indicated in the chapter on "Present mining conditions." Foreign engineers, after inspecting the process in this country, have adopted it in Europe. There, much extended and amplified, it is now an essential part of the more recent mining methods by which the engineers are able to recover all the coal; the excavated spaces are filled by the flushing method with crushed rock, sand, gravel, and soil obtained from quarries opened for the purpose, and also with ashes and city refuse, some of which is transported long distances over the surface to the flush pipes. Foreign engineers

find that when they thus remove all the coal, a gradual though small surface settlement results, the amount of which depends upon the depth and the thickness of the coal. In this country, however, we can not hope to profitably use such expensive mining methods as may obtain abroad, because the cost of labor in the United States is very much greater and the market price of coal very much less than in Europe. The appearance of culm flushing is shown by Plate 26.

### COGS.

It is frequently necessary in the course of mining to make use of some roof-supporting device that may be quickly constructed and is withal possessed of great strength. The timber crib filled with mine rock—known in mining parlance as a "cog"—has been found to answer these conditions in a very satisfactory manner, and is extensively used in all coal-mining districts. The cog consists simply of a rough crib of stout logs placed one above the other, loghouse fashion, the spaces between the logs being chinked and the interior being filled with rock from the mine. (See Pl. 27 A.) This construction is quickly erected, and possesses great strength. course it is not permanent because the timbers decay in a few years. Cogs are mainly used for the purpose of stopping a settlement, squeeze or creep which the mine foreman knows to be imminent or in progress. A view of a squeezed area in the Dunmore bed is shown in Plate 29 A. When sufficient cogs are placed in proper localities the strata above the bed will frequently crack through to the surface, and the progress of the squeeze or creep will thus be stopped.

### GOB PIERS.

Gob piers are pillars built of such refuse rock as may be readily found in most mines—mainly bony coal, fire clay, and slate. Such rock is mostly soft and does not possess very great compressive strength. Some of these piers have a square outer or inclosing wall, and are filled with mine refuse shoveled into them. In others the interior is laid up by hand and the rocks are more carefully compacted by filling the voids with fine mine refuse.

A great many such piers have been built under localities in the city of Scranton for the purpose of supporting the roof under valuable surface improvements. (See Pls. 27 B and 28.) The value of such piers, that is, their supporting strength, depends upon the compressive strength of the materials of which they are constructed. The value will be greater if the voids between the larger pieces are filled with the small rock and shoveled material from the mine.

### GOB STOWAGE IN ROOMS.

Most coal beds consist of interstratified layers of coal, fire clay, slate, and bony coal; the three latter, of course, compose the prin-



A. GANGWAY CUT THROUGH CULM FLUSHING, OXFORD MINE.



 ${\it B.}$  Gangway cut through flushing, culm standing as a vertical self-sustaining wall, oxford mine.



A. TIMBER AND ROCK COG, IN BELLEVUE MINE.



B. GOB PIER IN DUNMORE NO. 2 BED, NATIONAL MINE.

cipal refuse material of the mine. In all the mining methods adopted under the city of Scranton, all the material of the coal beds that is not coal is laid aside as refuse and stowed away in the chambers, either on one side or on both sides of the mine tracks. In thin beds where it is necessary to remove some of the roof rock or take up some of the floor of the mine in order to obtain height sufficient for the mules and the men to travel along the roads, much mine refuse is produced, which is also stowed in the chambers. In beds less than 4 feet thick many chambers are filled with mine refuse or gob, as it is more familiarly termed, from floor to roof. In places this gob is merely thrown in carelessly, or is shoveled in; in other localities it is packed as tightly as possible by hand. It frequently happens that the whole chamber from pillar to pillar is packed full of mine refuse. Where there is much interstratified fire clay or bone in the coal bed there will be larger quantities of the gob, and the thinner the bed the greater will be the quantity of mine rock raised or taken down for roads. Consequently, this stowage of gob in the rooms of the mines under the city of Scranton becomes an important item when the support of the surface over these coal beds is considered. As in the case of the gob piers and the cogs, the supporting value of stowed gob depends upon the compressibility of the material of which it is composed.

### CONCRETE AND MASONRY PIERS.

The above methods of artificial support already mentioned are comparatively cheap to install. Some other methods of support used in the city of Scranton are concrete and sandstone piers. In these the material for construction has been introduced from the surface (through bore holes in the case of concrete or through shafts from the surface in the case of blocks of sandstone), and in the mine has been wrought into substantial piers by the use of cement. (See Pl. 29 B.) Though these forms of piers are much more substantial than those previously mentioned, they are also much more costly; consequently fewer of them have been installed.

### IRON PROPS.

In one place, namely, in the Big bed under the Central High School building in this city, a number of iron props or posts have been installed as additional roof support. There has been no subsidence of pillars in the locality where they have been used; therefore the supporting value of the props has not been tested and their efficiency is largely a matter of opinion. In any case they are costly to install, and it is entirely probable that much more efficient means might be used for the same purpose at less expenditure.

### TESTS OF ROOF-SUPPORTING DEVICES.


### COMPRESSIVE STRENGTH OF ANTHRACITE.

In 1903 an exhaustive series of tests was conducted under the direction of a committee of the Scranton Engineers' Club for the purpose of determining the compressive strength of anthracite coal. The report of this committee on tests is printed in an appendix (see p. 77) to this report. The results, however, may be summed up briefly in the statement that a pressure of 216 tons per square foot will cause the average ordinary mine pillar to begin cracking, and a pressure about twice as great (432 tons per square foot) will crush it to powder.

This general statement, however, does not apply equally to all coal beds, for the tests prove a great variation in strength, even between different parts of the same bed. In some instances the weight required to crack the pillars was as low as 30 tons per square foot.

### TESTS AT LEHIGH UNIVERSITY.

In order to test the value of the several artificial devices for supporting the roof of a coal mine, as well as to search out an inexpensive combination of materials which might be more cheaply installed and withal more permanent and efficient, and better adapted to certain localities than some of those mentioned, we prosecuted a series of tests at the Fritz engineering laboratory at Lehigh University, South Bethlehem, Pa., the results of which are also given in an appendix (see p. 83) to this report. A tabulated summary of the results follows, and from it mining engineers may readily compute the supporting value of any particular construction.



A. A GOB PIER IN CLARK BED UNDER CENTRAL HIGH SCHOOL BUILDING, PINE BROOK MINE.



 $\it B$ . SIMILAR PIER WITH FLUSH PIPE PASSING THROUGH SHOWS SUPERFICIAL CHARACTER OF MORTAR POINTING.



A. VIEW IN SQUEEZED AREA IN DUNMORE BED, LEGETTS CREEK MINE.



B. SANDSTONE AND CEMENT MASONRY PIER IN DUNMORE NO. 2 BED UNDER SCHOOL NO. 15, NATIONAL MINE.

TABLE 3.—Results of tests of compressive strength of various forms of roof support.

Jo o'N		Net to	Net tons per mquare foot required to produce compression of—	iquare foot requi	ion of -	red to p	roduce	Compression and load (tons	ad (tons	Damoska
test.	Construction tested.	1 per cent.	3 per cent.	5 per cent.	10 per cent.	20 per cent.	30 per cent.	test.		Avenues nos
2	Rectangular piers of mine rock		0. s. x :0	1.4	11.2.7	25 E	38.5	Compression, 31 p	per cent;	Average construction; voids not filled. Well constructed; voids filled with small
624	Pimber crib filled with mine rock		9	1.37	5.11	9.3	2.5	49	per cent;	Average construction.
ည ထိ	Pile of small-size broken sandstone and sand. Pile of broken sandstone, large pieces		3.6	1.6	4 9.1	13.5	33 %	on, 45 on, 41	per cent;	In these tests the material was not confined but was free to externed laterally.
r- x	Pile of coal-measures sandstone similar to No. 6.	0.8	ei T	3.5	6.	33.4		Compression, 27 p. load, 56. Compression, 63 p.	per cent;	(See appendix, pp. 84-86.)
0			33.33	5. 55	13.32	46.6	98.6	n, 35	per cent;	
10	Broken sandstone and sand in cylinder		55.	5.77	24.42	308.5	:	n, 13	per cent;	
= = =	ith waterinder, partly dried	4 6	- 36 - 36	1.86	5.32	10.8 5.50 138.7	884	i i	per cent;	In these tests the material was confined and could not expand laterally. (See appendix, pp. 85-88.)
13	(average of two tests).  Dry sand in cylinder	8.	60	5.27	33.3	129	499	Compression, 32.2 p	32.2 per cent;	4 4 4
14	Wet sand flushed in and partly dried	- S.	39.3	67	173.8	555.4		1,	20.75 per cent;	
15	Concrete made of cement, sand, and gravel: 4 months old; 1 barrel Portland council to centerle cubic varieties of part centerle to seven parts sand and gravel; piers 3 inches by 2.81 inches by 3.55 Inches high.	Crae	Cracked.	Gradu	ally erus	hed to p	ieces un	Gradually crushed to pieces under continuous load of 45 tons.	f 45 tons.	This test was made at the Dickson Works of the Allise trainers Co. in Secanton, by William (critith.

### DRY FILLING.

Although we recognize that the flushing process is the most substantial method for artificially supporting the roof of coal mines, and that it is also universally suitable for thin or thick beds and deep or shallow beds, nevertheless the method is not always applicable or convenient. There are many localities in the coal mines where it may be either preferable or permissible to resort to some of the other less efficient or less costly methods of roof support, which for one reason or another are more adaptable to a particular locality. Therefore we refer to the improvements that may be made in the different methods of dry filling.

### IMPROVED METHODS OF GOB STOWAGE.

Formerly the gob of coal mines was disposed indiscriminately over the chamber at the side of the roadway, mainly for the purpose of getting rid of it at as little cost as possible. A casual inspection of the comparative table of tests on page 55 will show that wellconstructed gob piers are much stronger than those indifferently built. It is also evident that in supporting the roof of coal mines, as well as in other matters, "an ounce of prevention is worth a pound of cure." The effort, therefore, should be to prevent the first small settlement, and the way in which to accomplish this effort as far as possible in the matter of stowage will be to pack the rock fragments carefully and tightly against the sides of the pillars from floor to roof, irrespective of the horizontal area occupied, and to use the fine refuse, so far as may be, to fill the voids. If the gob now contained in the thinner seams under the city of Scranton had been carefully packed so as to completely fill the space from floor to roof it would not only reinforce and preserve the strength of the coal pillars, but would present very much greater resistance to pressure and would be a much more efficient roof support than is afforded by the usual present stowage with 1 to 2 feet of space between the top of the stowed gob and the mine roof.

In some beds now working there is a surplus of mine rock which can not be stowed in the chambers and must be hauled out into other parts of the mines. If it is determined to continue thus to stow this material instead of hauling it to the surface and grinding it for flushing purposes, as has been previously mentioned (see p. 55), the purpose of roof support would be better served if the places for depositing this surplus stowage were selected with reference to the weak parts of the mines, or with reference to the support of the ground under some particularly valuable surface improvement.

Commendable work is being done along this line at the Cayuga mine of the Delaware, Lackawanna & Western Railroad; the pillars

are being extracted in a surface bed and the space formerly occupied both by the chambers and the pillars is being completely filled with surplus rock taken from a lower bed.

### BLASTING ROOF AND FLOOR IN THINNER BEDS.

It is a well-known fact that loose rock occupies one and two-thirds to two times the volume of the same weight of solid rock. In other words, if a cubic yard of solid rock be broken to pieces the pieces will occupy a space of 1<sup>2</sup>/<sub>3</sub> to 2 cubic yards.

We have conceived the idea of taking advantage of this fact for the purpose of cheaply producing an adequate roof support for certain classes of coal beds under the city. So far as we know, this method, in its entirety, has never been used before in any coal-mining

district, and the suggestion is here made for the first time.

The process would be applicable to beds less than 6 feet thick and so situated that the shock of heavy blasting would not produce ruptures of the measures supporting adjacent coal beds. It consists simply in blowing up the floor of the mine to a depth equal to the thickness of the bed, and blowing down the roof of the mine directly over, to a height equal to the thickness of the bed. This would produce a total thickness of loose rock equal to three times the thickness of the coal bed. The rock would be well packed together and have great supporting power, and the process would be comparatively inexpensive.

This method might be adopted throughout the Dunmore and other thin seams, by blasting down the roof and raising the floor in the abandoned rooms or the roadways between the gob piles in the chambers. Wherever it is applied the effort should be to completely fill the whole width of the chamber or roadway from pillar to pillar, so that the loose rock will be confined between the pillars, thus greatly increasing its resistance to compression. The value and supporting power of this method of roof support and of other methods will be referred to below.

### GOB PIERS AND TIMBER COGS.

There are localities under the city of Scranton where it has been deemed advisable in the past to build gob piers for the support of the roof overlying certain surface beds. The Lehigh University tests mentioned in this report show that this method of support lacks the merit of strength. The piers are very compressible, and as they have been built heretofore their supporting value is small. Their efficiency would be greatly increased, as shown by the differences between test No. 1 and No. 2 (pp. 83–84), by building them in circular form and carefully filling all the voids between the larger pieces with smaller particles of shovel stuff.

### CONCRETE PIERS.

During the progress of this investigation many persons have called our attention to concrete piers as suitable for firm roof supports. This material is so costly, however, that we have hesitated to recommend it except perhaps in special cases where very valuable surface property requires unyielding support and the expense of such support is no object.

We have tested the strength of one sample of concrete composed of about the cheapest good materials available for this locality, i. e., cement, sand, and gravel. The results of this test are shown in Table 3, test 15, and Table 4, test 14 (pp. 55,59). It will be noted that such concrete is firm and comparatively unyielding up to a certain maximum strength sufficient to cause about 3 per cent of compression and cracking, beyond which a much less weight will crush it to powder. This latter characteristic is an exceptionally bad one for a mine roof support, because such piers are liable, under the excessive stress due to a general squeeze, to collapse quickly, and thus permit the sort of caving that resembles a small though severe local earthquake in its suddenness and excessively damaging effect on the surface improvements.

### DRY FILLING WITH BROKEN STONE OR SAND.

For the construction of isolated and more substantial low-cost piers in the surface beds under the city, to take the place of the gob piers for the purpose of the local support of valuable surface improvements where general flushing is not convenient, we strongly recommend the filling with broken stone or sand, or a combination of these materials, through bore holes from the surface.

Filling of this sort should be spread out by hand in the inside of the mine so that it completely fills the whole width of the space from pillar to pillar, and thus, being more or less confined has its supporting power increased. If broken stone is used the relative proportion of the voids should be ascertained and an amount of sand, coal ashes, or other fine material added sufficient to fill these voids.

By this method one bore hole 4 to 6 inches in diameter would be necessary for each pier, and inasmuch as these materials, if flushed in by water, are much more closely packed and have from ten to fifteen times the compressive strength of dry filling, it would always be wise, if water is handy or is not too costly, to flush the material in, using in some cases the city water, or the water from the gutters during the storm seasons for the purpose. The more sand there is in the mixture the better it will be, for our tests have shown that clear river sand is the strongest and least yielding material available, if it is flushed into and confined in the limits of a mine chamber; moreover it is about the cheapest material obtainable for this purpose in Scranton.

### THE VALUE OF THE DEVICES FOR ROOF SUPPORT.

The following table sets forth the value of the above devices for dry filling, and also the value of the different materials that are available for flushing coal mines in this locality. The values are directly deduced from the results of the tests made by us at Lehigh University, and we think are sufficiently clear to be self-explanatory. We might add, however, that test 1 would represent the ordinary supporting value of gob piers or gob pillars. Test 2 represents the value of well-constructed gob piers, while tests 6, 7, and 8 set forth the supporting value of mine rooms filled with rock blasted from the floor and roof, as heretofore mentioned; and tests 12 and 13 indicate the supporting strength of fine materials, such as coal culm and river sand, if flushed in with water. At the bottom a comparison is made between the supporting value of the flushed culm and the flushed sand, and the concrete piers of the same nature as the sample tested.

Table 4.—Supporting strength of various forms of dry filling.

ind of material comprising the artificial supports.	me	asure ro	ck 1 fc	, in feet, o oot squa roof sup	re, neces		Remarks.
er cent of compression	. 1	3	5	10	20	30	
Rectangular gob piers, ordinary	Feet.	Feet.	Feet.	Feet.	Feet.	Feet.	)
. Circular piers of mine rock well con-							
Structed		46	75	146	292	512	
age construction		8	68	182	270	419	Free to expand
voids			20	53	124	298	laterally.
<ul> <li>Pile broken sandstone, 40 per cent voids, voids filled with sand</li> </ul>			21	53	186	465	
. Loose pile large size broken sand							
rock, 45 per cent voids		48	66	121	351	492	)
sand rock, 50 per cent voids	. 12	27	45	117	434	a 615	
. Mine room filled with broken sand- stone, 40 per cent voids		44	74	177	619	1,310	
. Mine room filled with broken sand-		7.7	12	2,,,	010	1,010	
stone, 40 per cent voids filled with		46	77	325	6,000	b 8,860	
. Mine chamber filled with dry coal							
ashes, 64 per cent voids	12	13 40	25 70	70 442	143 1,715	6,640	
. Mine room filled with river sand					1,110		
thushed in with water		522	891	2,310		r 8,860	
flushed in with water	. 32	118	190		1,822		
. Concrete pier, I part cement, 7 parts sand and gravel; 5 months old		1.092	under to 600	dually of continu	racked to lous load ock.	o pieces d equal	
esistance of flushed culmesistance of flushed sand		1 4.4	1 4.7	1 5	1 4		Comparative.

a 27 per cent settlement. b 23 per cent settlement.

c 20% per cent settlement.
d Worthless.

### SUGGESTIONS FOR IMPROVEMENT IN MINING METHODS AND PILLAR SUPPORT.

The solid coal remaining to be mined under the city of Scranton is mainly in the Dunmore beds Nos. 1, 2, and 3. These beds are from 200 to 600 feet below the surface under the greater portion of the city.

Future mining plans, we think, should provide for leaving at least 50 per cent of the coal in these beds on first mining, and the columnization of the pillars throughout all new mining as far as possible.

### FLUSHING.

Reference has been made to the practice, now quite general, of flushing culm into the mines. This is being done at nearly all of the collieries within the city limits, and the method and effectiveness of this kind of support was observed by personal inspection underground (see Pl. 26).

With reference to the tests made at Lehigh University of the compressibility of the several kinds of support now in use or suggested, we are of the opinion that a practicable method for the support of the overburden, utility and cost being considered, is flushing the openings with culm, ashes, sand, broken stone, material excavated from cellars, and other stuff of similar nature that can be reduced to a size small enough to be carried in pipes with water.

As before referred to, the flushing of mines for the support of the overburden has been adopted in Europe with marked success, both in the matter of support and recovery of all the mineral, the material used for filling being sand, loam, crushed slag, and crushed stone.

It is manifest that the quantity of culm available for flushing the extensive mine openings is insufficient, even if all of that now on the surface within the city limits, together with that produced in the preparation of the present output of coal were put into the mines.

According to figures we have assembled and supplemented with estimates, it appears that there has been extracted from the beds underlying the city, approximately 221,000,000 tons of coal and other material.

The workings under the city are, of course, not all open, large areas having been closed by general caves and squeezes. It is not possible to determine the proportion of openings that have been thus closed or filled, but a conservative estimate of the space now open would be that it probably does not exceed 50 per cent of the original.

The positive protection of all of the surface would appear to require the filling with some supporting material of all of the open spaces as rapidly as the coal is extracted; but such a scheme is, of course, impracticable. It therefore remains to determine about what

proportion of the openings to be flushed would afford reasonable protection. To determine this point definitely would necessitate a much more thorough investigation and more detailed surveys than were contemplated in the general investigation upon which we are now engaged. We would, however, express the opinion that conditions could be materially improved by the insertion of artificial pillars reinforcing the natural pillars of coal in blocks of from 1 to 5 acres at points where the danger of subsidence appears greatest; such artificial pillars to be arranged with some degree of regularity, so that the overlying strata between the artificial pillar supports would act as natural bridges. This suggestion is made in order to distribute the relief measures over as large an area as possible, and to keep the burden of expense within reasonable bounds.

The fact that the best and most practicable of supports is obtained by flushing refuse material into the openings having been determined, it remains to ascertain the sources of supply of this material, and the practicable methods of handling it.

We would classify the materials obtainable, in about the following order:

CULM FROM OLD AND FROM FRESH-MINED BANKS.

Culm is now being used for flushing mine workings. We make no further comment, excepting to refer to the test of its compressibility, and to the fact that we had opportunities to observe the methods of distribution of the material underground, and to note the apparent support given to the existing coal pillars and to the overburden.

### SURPLUS MINE ROCK.

The second source of supply of material, in the order of availability, we believe would be the surplus mine rock that is produced in the mining of the thin beds of coal where either roof or floor must be removed to make height. It was observed in most of the thin beds visited that considerable quantities of this material are handled, either being stowed in the chambers or loaded into mine cars and hauled to some distant point to be unloaded by hand into abandoned mine openings. While this stowage of gob affords some measure of support to the coal pillars and the roof, the compressibility of the material, as shown by the tests, is so great that the material if put in by ordinary stowage is practically useless as an effective support, particularly at great depths. We believe, therefore, that this material should be loaded into cars, hauled outside, and handled over an efficient dump and through crushing rolls of proper design for pulverizing hard materials. The ground material should then be flushed, with the culm produced at the mine, into the portions of the mine workings where it will do the most good.

In addition to this source of supply of filling material, it would probably be found practicable to install handling and crushing machinery at each of the mining operations within the city limits, to pick up refuse material, such as old rock banks, ash banks and slag, and to grade off humps and hills of earth and comparatively soft rock, and to treat this material in the same manner. The cost of handling and flushing such foreign material in connection with the going operations of the several mines, would, of course, be very much less per cubic yard than it would be in the case of an independent plant established for obtaining and handling flushing material elsewhere.

### RIVER SAND.

The next source of supply of material for flushing purposes, and one that we deem of considerable importance, is the Lackawanna River. It is a well-known fact that this stream of water carries in suspension large quantities of culm, sand, and loam at all times, and especially during the flood season. Of course it is impossible to determine without careful tests the quantity of this material in cubic yards, but we do not hesitate to express the opinion that there is enough of it, and will continue to be, to justify the establishing of settling basins and of a pumping plant for distributing the material thus impounded to points in the mine workings where artificial pillars are to be inserted.

To utilize this source of supply, it would, in our opinion, be advisable either to purchase, or to procure long-term leases on, river-bottom lands at various points where suitable catch basins could be excavated, and to procure a site for a central pumping plant for the purpose of handling this material. When such a plant is established, arrangements could be made to let down from the catch basins, at points upstream, the accumulated material; this would be carried by the stream to a central basin somewhere within the city limits.

We believe similar impounding basins on a smaller scale might be practicable on Roaring Brook, and that such material, if gathered at a higher elevation, might be flushed to near-by mine workings by gravity.

### CITY REFUSE.

Another source of supply of material for flushing purposes would be city ashes and refuse from the streets and catch basins; also material from cellar excavations, grading of streets, parks, etc., which of course would have to be put through a crushing plant and reduced to such a size that it could be handled by flushing. For the proper distribution of the material just mentioned it would be necessary to drill bore holes to the mine workings at convenient points in the city streets and alleys—preferably in the latter, because there would be less inter-

ference with traffic. The necessary water for flushing this material would, of course, be supplied from the central pumping plant on the river or from the Roaring Brook gravity supply.

### SAND FROM DISTANT POINTS.

Another important source of supply of material which we believe would be practicable would be sand and loam that the transportation companies should bring in from distant points along their railroads, where it can be most economically procured, in returning empty coal cars. This material would have to be dumped over a suitably arranged hopper and flushed into the mines with culm and other material.

A comparatively cheap and effective means for transportation of flushing material on the city streets to the shallow shafts and bore holes suggested would be to arrange with the traction company to haul the stuff in suitably designed hopper-bottom cars from the central crushing plant during the time of light traffic at night.

We would suggest the establishment of about four crushing plants so designed as to be easily knocked down and moved to other locations. The material to be handled by these plants should be taken from points where grading of humps and hills will result in the improvement of highways, parks, and private or public lands.

In this connection we would refer to the very extensive grading operations carried on in Seattle, Wash. A large section of the business center of that city was regraded mainly by the hydraulic method. Hills 100 feet high were cut or washed away, buildings were shored up or torn down, and the general level of the regraded section was lowered 10 to 30 feet. The material was flushed into Puget Sound by streams of water, and large areas of new land were formed over the low tide marshes along the bay shore. The expense was met by a general city-improvement tax.

### PLANS, SPECIFICATIONS, AND COSTS.

The general nature and wide scope of this report necessarily limit us to general plans, specifications, and estimates of cost. The rendering of detailed plans and specifications and of exact estimates of cost can be made only after careful and exact surveys under particularly ascertained conditions; such surveys should be obtained from the engineers who are to be in charge of the execution of the work recommended in this report, in case it shall be entered upon by the authorities. We therefore explain by way of specifications what will be necessary in our opinion, what we recommend to be done to ameliorate the present conditions, and the approximate cost thereof.

We have made careful investigations of the resisting power of the various devices thus far used for supporting the roof at various places under this city, and also of other devices we were cognizant of or have ourselves originated, but the supporting values of these various devices, as indicated in the tables of tests presented, have convinced us that the method of flushing material into the mines by means of water is the best and only well-tried method.

The method we have originated and experimented upon to some meager extent—that of providing roof support by simultaneously blasting the floor and the roof of the coal mine to form a permanent pillar from the débris resulting from the blasting—is an economical one, and has its advantages for certain special localities where the overburden is light. Still, the amount of compression to which the pillars of this sort would be liable is considerable and the extent of the possible disrupting effect of the heavy blasting upon the strata is unknown. Consequently, much more extended and practical experiments or tests of the method must be made before its value and importance as a roof supporting device can be established.

Therefore, the only method we feel like recommending, after a

careful study of the conditions, is the flushing method.

As before mentioned, the best protection for the surface from caves would require the complete filling of the mine openings with culm, sand, or other form of material, and even then there would be more or less subsidence if pillars were removed and filled-in material were substituted. The excessive cost of completely filling the openings, and the tremendous magnitude of the project makes this plan prohibitive.

In our opinion reasonable protection can be afforded by the introduction of artificial pillars of flushed material, reinforcing the natural coal pillars to the extent of relieving them of one-third of the overburden. Such artificial pillars to be located about as follows, reference being had particularly to the plans shown in Plates 1 to

24, which are part of this report.

Owing to the great importance of substantial support for school properties, we would suggest that in each bed mined under any school, for at least 50 feet outside the lot limits, or rather for a distance equal to one-half the depth of a bed below the surface, the openings be flushed full of the best available material. The school properties—being located in all parts of the city, and over widely varying mining conditions—would afford good starting points from which to space the additional artificial pillars necessary for the protection of the surface elsewhere.

Following out the above scheme in systematic order, we would recommend the installation of artificial pillars of flushed sand or flushed culm at each street intersection where the city blocks are of the usual size, about 5 acres, the present coal pillars to remain. In the case of all coal beds of greater depth than 150 feet, such pillars,

if at the block corners, might be sufficiently near together; but for less depth the strata might be too weak to bridge the whole width of a city block, even though the usual coal pillars were left in place. Therefore it would be better, in the latter case, to install pillars in the center of each block also, in which case the pillars should each be about one-half as large as if located at the block corners only.

In locating artificial pillars intermediate between school properties, advantage should be taken of those places already flushed by the coal companies. It will be found that considerable filling of this sort has been done.

The question of the size and consequent cost of artificial piers is approached by us with much hesitation and caution, because, although we have secured considerable valuable information on the subject through the underground investigations we have been making, we know that in the last analysis the size of these piers must be estimated from the results of the testing we have done at the Fritz engineering laboratory at Lehigh University. In view of the great magnitude and importance of the question at stake, we realize that these tests, which are the first of the kind that have ever been made, are very meager and do not constitute a sufficient foundation upon which to base final conclusions.

Therefore we have decided to use a factor of safety of two. In other words, the size of the pillars we have recommended is twice as large as the tests indicate might be necessary. These tests are subject to check by further tests and other data that may be procured later, either through the working out in practice of the recommendations herein made, or otherwise, but which have not been and are not now available to us.

The size of artificial pillars should be determined by the local conditions found at the exact spot chosen upon inspection by the engineer in charge of the work. Subject to the above observations, the horizontal areas of artificial piers of flushed material confined in mine rooms are indicated in detail by the table following.

Table 5.—Horizontal area, in square yards, of artificial mine pillars of confined flushed culm or flushed sand required under various permissible compressions to sustain one-third of the overburden of one city block of five acres, at various depths.

Ultimate			Depths.				
uniform compres- sion	25 feet.		50 fe	eet.	100 feet.		
permitted.	Culm.	Sand.	Culm.	Sand.	Culm.	Sand.	
Per cent. 3 5 10	3, 424 2, 122 848	800 452 176	6,848 4,244 1.696	1,600 904 352	13,696 8,488 3,392	5,200 1,808 704	
	200	feet.	400 1	leet.	800	feet.	
3 5 10	(a) 16, 976 6, 784	6, 400 3, 616 1, 408	(a) (a) 13,568	12,800 7,232 2,816	(a) (a) (a)	(a) 14, 464 5, 632	

a Openings filled.

Notes.—1. Up to 3 per cent compression, piers of sand and gravel concrete might be only one-half the size of sand piers, but for weights that would produce greater compression they are worthless.

2. One city block of 5 acres covers 24,200 square yards.

3. In fixing upon the amount of compression that might be permitted, consideration should be given to the fact that where several beds are to be filled, the total settlement will be several times as great as for the bad of the wrence thickness.

one bed of the average thickness.

4. It will be noted that complete filling with culm is necessary for the compression mentioned at depths of 200 to about 500 feet, whereas for greater depths the compression due to the greater weight would be excessive. Sand, on account of its greater strength, is suitable for filling all beds at all depths under the city of Scranton, and is therefore to be preferred.

The location of bore holes or shafts through which to flush the material must be determined by the engineers in charge of the work. Several of the blocks can be reached from the foot of each bore hole or shaft.

In many of the beds on the west side large areas of the mines are inaccessible, and conditions are of such a character that we are thereby limited to the most general specifications. We would suggest first, that the school properties be taken as starting points, and under each of them, namely, Nos. 13, 43, 12, 29, 32, 32 annex, 14, 31, 16, 17, 18, 19, 41, 21, 40, 24, 22, 23, 25, 26, and 44, artificial piers of flushed material be installed wherever possible, these piers to extend well beyond the lot lines (at least 50 feet outside) in all the beds that have been worked, beginning with the lowest bed; and that when a pillar is built in that bed, the overlying beds be filled in order.

Early attention to schools Nos. 12, 23, and 29 is especially important. In locating the supporting pillars advantage should be taken of the large areas that are caved and closed in the Clark, New County, Big, Rock, and Diamond beds, and of other parts that are already flushed. The best results will be obtained, of course, by flushing the lowest beds first and proceeding upwards, care being taken to locate the new pillar in the upper seam over that already in place in the seam below.

# COST OF SUGGESTED PROTECTIVE MEASURES.

The absence of accurate and conclusive data, and the many uncertain factors entering into this general statement make any submitted figures approximate only. Assuming that all the sources of flushing material hereinafter mentioned in the order of their importance and value—first, sand and loam brought from a distance in returning empty coal cars; second, culm from breakers and washeries; third, crushed mine rock, gob, etc.; fourth, culm and silt from Lackawanna River and Roaring Brook; fifth, crushed rock from three or four plants (which might be established by the protective commission)—are utilized in regular and systematic order, and that the methods of procuring water for flushing, etc., as suggested, are put in effect, we would in that case estimate the cost of the measures suggested about as follows:

The necessary plants and machinery for expeditiously excavating and loading the sand and filling material at distant points, and the plants in the city for unloading and transferring the material to the traction company cars for delivery at night to the various flushing points; the building of the dam and pumping stations on the Lackawanna River and the necessary storage dams at various points on the river above the city, for catching surplus sediment during seasons of high water; the dam in Roaring Brook, above the city level; the necessary means to conduct the water to the more elevated parts of the east and south sides; and a portable crushing plant to be located at the flushing points to crush the larger particles of sand, coal ashes, and city refuse that may be delivered and mixed with the flushing, would cost approximately \$500,000.

The necessary facilities outlined above for the expeditious and economic handling of material and prosecution of the work having been provided, it is our opinion that artificial piers may be established in various beds at about the cost shown in the following table, using the factor of safety (2) mentioned above.

Table 6.—Approximate cost per foot of coal-bed thickness of artificial mine pillar of confined flushed culm or flushed sand required under various permissible compressions to sustain one-third of the overburden of one city block of five acres, at various depths.

Ultimate	Cost.								
uniform compres- sion	Depth,	25 feet.	Depth,	50 feet.	Depth, 100 feet.				
permitted.	Culm.	Sand.	Culm.	Sand.	Culm,	Sand.			
Per cent. 3 5 10	3 5 8286 176		\$572 · 352 140	\$532 300 120	\$1,144 704 280	\$1,064 600 240			
	Depth,	Depth, 200 feet.		400 feet.	Depth, 800 feet.				
3 5 10	a \$2,016 1,408 560	\$2,128 1,200 480	(a) (a) \$1,120	\$4,256 2,400 960	(a) (a) (a)	a \$8,070 4,300 1,920			

a Filled.

The approximate cost per foot of bed thickness for each acre of complete flushing under schools and elsewhere, to take the place of pillars, if removed, would be:

For culm below level of river	\$405
For sand above or below river.	1,615

If, in the case of the coal beds 150 feet or more deep, the board of control concludes to be satisfied to relieve the present pillars under the schools of about one-third of the burden they now sustain, the approximate cost of so doing, per foot of bed thickness for each acre thus protected, will be about one-fifth of the cost shown in Table 6, for the same depth, material, and settlement. For example, to relieve the present pillars of the Clark bed, which is about 200 feet deep under the central city and hill sections, of one-third of the weight they now sustain, allowing 5 per cent as ultimate permissible settlement for the coal-bed roof, would cost per foot-acre of coal bed, about \$280 for culm flushing, if the piers are below the river level; or \$240 for sand flushing, whether above or below the river; and since this coal bed is about 7 feet thick, the total cost of such piers would be about \$1,960 and \$1,680 per acre, respectively.

The above table is estimated on the supposition that the pillars of flushed culm would be installed only at points that are in coal beds below the level of the river (so the necessity of pumping culm to an elevation above the river would be avoided) and that piers of flushed sand would be installed in coal beds at locations that are above the level of the river, or at any location where such sand pillars would be convenient and not more costly than culm pillars.

It will be noted that there is no large difference in cost between culm or sand. This, of course, is on account of the greater efficiency

of the sand, a less quantity of which is required to give the same

supporting power.

It will be apparent that much of this work can be done by the systems of flushing already in service at the several mining plants, and that in order to accomplish the best results in the most economical manner, the plans of the city mine-cave protective commission must be made in harmony with the already established systems of the mining companies. It is manifest that all underground work should be done in cooperation with the coal companies and that the water flushed into the mines must be pumped by the plants already installed, with such additional equipment as may be found necessary.

Therefore, this matter of harmonious plans and procedure between the coal companies, the city, the school authorities, and the public is essential to the successful carrying out of any relief measures that are herein or may be hereafter suggested. It is a fact that should be evident to all that the prosperity of the city and the community is to a large extent dependent upon the coal companies, so that drastic laws or regulations that may curtail the mining of coal will necessarily react on the prosperity of the community, whereas any ameliorating plans or compromises which it may be possible to effect between the city and the mining companies tend to prolong the life of the mining industry in Scranton and vicinity, and should be promoted.

It should, therefore, be the aim of all persons interested in minecave protective measures and of the companies operating the mines to adopt plans that will best conserve the welfare of all concerned.

The expenditure for the work would, of course, be distributed over many years, the relief measures being applied at the points most in need of protection and as rapidly as proper arrangements could be

effected and the necessary details, surveys, etc., prepared.

For the business-like carrying out of the plans suggested, it is recommended that a protective commission be established, consisting of not less than three nor more than five men representing the city authorities, the school board, and the coal companies; this commission to have full and complete authority for the execution of the plans, after approval by the proper legal action. The commission should employ an engineer as active manager of the work, who should devote all his time to the service.

#### GENERAL CONCLUSIONS.

In concluding this somewhat lengthy report, we are of the following opinion:

First. Speaking broadly, the surface of the city can be supported by the methods recommended, and at a cost not in any sense prohibitory when considered with relation to the value of the property and the activities for which support is absolutely essential. Second. Although there are points in the city, as indicated in the detailed report, where at the present time in our judgment there is distinct and immediate danger to life and property, yet the total area immediately threatened constitutes but about 15 per cent of the entire area of the city, and the danger is mainly from workings in surface beds.

Third. On the west side the beds of the middle series are thick and close together and the pillars are not columnized, creating a dangerous situation where the workings have not been closed by previous caves. Particular areas thus threatened can not be definitely specified on account of the inaccessibility of much of the mined-over area. Detailed investigation should be made of the portions of the mines not already closed. Relatively, we do not believe that a large part of the territory mentioned is threatened because so much ground has been already closed by caves.

Special attention is called to the conditions under schools Nos. 13,

23, and 29. They should be attended to promptly.

The beds of the lower series, namely, the three Dunmores, are so thin and so far below the surface that with the usual system of mining we do not think they constitute a serious menace to the improvements on the surface, except along the margin of solid blocks of unmined coal and near the outcrops. In the deep-lying parts of the Dunmore beds we believe these solid blocks should be mined.

Fourth. It would seem, therefore, to be not only the part of wisdom, but absolutely obligatory to commence at once to give support to the points menaced, and thereupon proceed upon a general policy of giving support to the entire area of the city; for it must be borne in mind that with the mining activities that are constantly going on other and additional points of danger are not only liable to, but in all probability will, develop with each passing year—it might almost be said with each passing month.

Fifth. Where the owner of the surface has undoubted right to the support thereof by coal pillars, in our opinion he could permit the removal of such pillars; the value of these would under average conditions pay for such artificial support as we have recommended, assuming that the pillars were mined and the support constructed by the same operating company. This observation, however, is based upon the assumption that in such case the operating company would be one of the large transportation companies, inasmuch as while there might not be a profit in the immediate transaction of mining the pillars and installing the support there would, of course, be a profit to such companies in carrying the coal to market.

Sixth. Culm flushing should be used only in coal beds having light cover, up to 200 to 500 feet, according to the amount of settlement expected. But sand, being four or five times as strong as culm, is better, is suitable for all beds under Scranton and should be preferred.

Seventh. We believe that the conclusions adduced from the tests made, and the calculations and tabulations based thereon, are reasonably reliable; yet we desire to record the opinion that there are conditions existing in the mines to which they might not apply—for instance, in localities where several seams of coal are separated by a thin layer, or layers, of shale and slate, or even sandstone, and the pillars in the several seams are not over one another, and it is proposed

reclaiming all or any part of the pillars.

Even though an application of the above tables might appear to fit the conditions, we believe that the only permissible procedure would be to first fill with flushed material all of the openings in the lowest bed of the series and then fill upward until all the beds are filled, care being taken to have the flushed areas over one another. After all of the openings in all of the seams have been filled, the pillars in the uppermost seam may then be attacked; as each pillar is removed, the space should be at once filled. No pillar reclamation should be permitted in any of the other beds until all of the pillars in the upper bed have been removed and the overburden has come to rest on the flushed material; then the pillars in the next lower seam may be attacked and handled in like manner.

# NOTES ON SAND FOR MINE FLUSHING IN THE SCRAN-TON REGION.

By N. H. DARTON.

# INTRODUCTORY STATEMENT.

This report presents the results of field studies in the vicinity of the city of Scranton, Pa., to find some convenient sources of sand to be used for filling chambers in coal mines under the city. Attention was given only to material that lies at higher altitudes than the workings and might be hauled down grade or transported by water to the mines. Moreover, it was recognized that inasmuch as the final means of transportation underground would be flushing with water the material would have to be in granular condition. The sources of supply are glacial till of various kinds and the rocks of the coal measures or underlying formations. The latter would have to be quarried and crushed; the pebbles and bowlders of the till could be crushed or discarded.

# ROCK FOR CRUSHING.

The entire anthracite region is underlain by rocks that contain a large proportion of sandstone suitable for crushing, and can yield an angular sand of great strength. It is estimated that sandstone of moderate hardness can be crushed into coarse sand for \$0.50 to \$0.60 a ton, including quarrying. This estimate is based on a cost of \$1.60 per ton for coal for power.

One of the most conspicuous rocks in the Scranton region is the Pottsville conglomerate. It immediately underlies the coal measures and outcrops in belts of varying width in the mountain slopes on both sides of the coal field. The greater part of this rock is too hard to be cheaply crushed into sand. It is underlain by greenish and gray sandstones, mostly soft, and in places by red shale. These sandstones and the shale can be more easily crushed. The most extensive ledges of sandstone convenient to railroad haulage are in the gorges of Roaring Brook east of Scranton, and of Leggetts Creek, northwest of the city. Along the gorge of Roaring Brook from Moscow to Dunmore there are continuous high ledges, many of which rise 500 to 700 feet above the creek. This gorge is followed by the Erie and the Lackawanna railroads with a heavy down grade into Scranton. There are many localities favorable for the establishment of quarries and crushers, and the possible tonnage of product is practically unlimited. It is certainly sufficient to fill all coal workings

under the city of Scranton. One crushing plant is already in operation by the Nay Aug Stone Co., just below Nay Aug station. However, a large amount of stone is available farther down the gorge and therefore considerably nearer Scranton. Crushed rock from a quarry in this gorge could be loaded directly on empty coal cars and hauled down grade into Scranton.

The sandstones underlying the Pottsville conglomerate in the gorge of Leggetts Run present a thickness of about 800 feet, rising in high walls along the gorge 2 miles northwest of Providence. There is here available a very large amount of sandstone of moderate hardness, admirably located and physically well suited for sand for filling. The product could be hauled down grade on the Lackawanna Railroad or on the trolley line which follows the bottom of the gorge.

The hydraulic transportation of the fine crushed stone to the mine was not especially considered, but both on Roaring Brook and on Leggetts Creek the waters are so impounded that perhaps they are not continuously available for hydraulic work. The sandstones under the Pottsville conglomerate are exposed also in the valley of Meadow Brook in the southern part of Scranton, where they are utilized by the crusher now in operation. This crusher belongs to the Meadow Brook Co. and has a capacity of about 300 tons a day. Crushed stone from the exposures in this vicinity would be handled by the Laurel line and the Erie Railroad; possibly, also, it could be flushed down the bed of Meadow Brook, but the conditions are much less favorable for such transportation than on Roaring Brook or Leggetts Creek.

There are extensive ledges of the sandstones of the coal measures in the high ridge extending west from Lackawanna River, just east of Holden, where a moderately large amount of gray sandstone is available. Another ledge appears on the north bank of Leggetts Creek, near its mouth. This ledge has been quarried extensively, but the quarry could be extended over 1 or 2 acres to the north. To the northwest it passes under the huge pile of culm from Leggetts Creek colliery. Sandstone ledges outcrop prominently in the high ridge on the east bank of Lackawanna River, a half mile east of Dickson, and a crusher could be established at this place with fair advantage, as the ledges are directly over extensive coal workings.

# GLACIAL TILL.

The till left by the great continental glacier extends across northern Pennsylvania, and forms a mantle of irregular thickness and varying composition. In the Scranton region it covers much of the surface to a considerable depth, excepting the mountain slopes and summits, where it is thin or absent. The underlying coalmeasure rocks also appear in places along the lower slopes of the

Lackawanna Valley, and near the river there are terraces of later alluvium. Where the till is thick it rises in hummocky ridges that are generally thickly strewn with bowlders. Scranton is built mostly on slopes of till, terraces of rearranged till material, and later beds of sand deposited by Lackawanna River.

The glacial till consists of a mixture of sand, clay, loam, gravel, and bowlders in varying proportion. In the Scranton region the till contains little clay and a predominance of sand, but I saw no extensive deposits of pure sand. Gravel and bowlders exist in all the exposures and their proportion is seldom less than 50 per cent. Some streaks of pure or pebbly sand occur, but they are local and would not yield a large supply. If the sandy till were subjected to washing by hydraulic jets and sluiceways the sand would all be separated from the bowlders. This till, in my opinion, is the best source of sand in the region; it can be removed at many places where the cultural and hydraulic conditions are favorable. One of the most desirable sources of supply would be from street grading, since the result would be both a large volume of sand and a city improvement. The bowlders remaining after the sand had been carried off could be crushed into sand and washed into the sluicewavs.

In the northern part of Providence there are several prominent hills or knolls of sandy till which could be leveled to advantage. They lie between Bloom and Keyser Avenues, west of West Market Street; another knoll lies just east of West Market Street, north of Clark Avenue. These knolls rise from 50 to 60 feet above the average grade of the streets and would furnish nearly a half million tons of mate-The material contains about 50 per cent of sand; the remainder is gravel that would have to be crushed in order to be utilized for flushing. Two very much larger masses of till lie on the mountain slope a short distance north and west of this area and another extends up the ridge on the north side of Leggetts Creek. Each of these three areas contains about a million tons of sandy till. Similar masses of till lie on the lower slopes of the mountain west of Keyser Creek, the largest one extending to within a few hundred yards of the Hyde Park colliery. There is a rock core to this largest mass, but the till is not less than 50 feet thick, and the indicated total tonnage for this one area is about 15,000,000 tons. The deposit is mostly sandy till with only a small proportion of clay; it averages nearly 50 per cent sand. The remaining material is coarse bowlders, mostly of hard rocks, which might either be crushed into sand or left on the ground after the sand is washed out. There is in this vicinity only a meager supply of water for hydraulicking.

An extensive area of sandy till is just east of the Holden colliery. It underlies land that for the greater part is not covered by buildings,

and has an estimated tonnage of about 5,000,000 tons. The material contains about 50 per cent of sand, with gravel, bowlders of hard rock, and very little clay.


One of the most desirable bodies of sandy till is on the estate of William Miles, just west of Olyphant. The land is not built on and is adjacent to various lines of railroads. A moderate amount of water is available for sluicing in a near-by creek, and water possibly can be had from the river also. The till area measures about 2,000 by 1,500 feet, and the thickness of material available is about 30 feet. These measurements indicate an aggregate of nearly 5,000,000 tons. The proportion of sand is variable, but in places it exceeds 60 per cent. It is being dug to a small extent for sand for local building purposes. There is not sufficient clay in any part of the area to be disadvantageous, and the gravel and bowlders could be crushed, if desired.

# ALLUVIUM.

Along the Lackawanna River extend low alluvial terraces, which are underlain by sand that in greater part contains only a small proportion of coarse material. Unfortunately, however, the sand area near Scranton is covered with houses or is held for its value as building lots, so that the sand is not available except at a few points. As the terraces are very low, the tonnage of sand that could be obtained is not great. It is possible that the water of the river could be used for sluicing this material, but because of the great variation in the amount of water available during the different seasons of the year, the conditions are not altogether favorable. The location of the railroads along the river complicates the problem of removing the sand. Doubtless this source of material would not be as advantageous as the sandy till or crushed rock.

# RIVER SAND.

The most extensive deposit of sand in the northern anthracite coal basin is under the deep valley of the Susquehanna River from Pittston to Nanticoke. Its width averages 2 miles for a long distance and its thickness varies from 100 to 200 feet in greater part. There are many places where this material could be lifted from the river channel by dredges and loaded on empty coal cars. In the river and harbor work of the United States Engineers office and in Panama Canal excavations sand is dredged from depths of 20 to 40 feet and carried in pipes 1,000 to 2,000 feet at a cost of 3 to 5 cents a cubic yard. The cost of handling sand from the Susquehanna River is a matter for local engineers to determine. The sediment brought down by the river, especially in time of flood, would rapidly refill excavations made by dredging.



# APPENDIX.

### COMPRESSIVE STRENGTH OF ANTHRACITE COAL, a

Owing to the general lack of knowledge among the engineers of the anthracite coal field as to the compressive strength of anthracite coal, and in view of the very important matters relating to the economy of mining of anthracite, which depend directly upon this subject, the Scranton Engineers' Club, in July, 1900, appointed a committee to make a general investigation of the compressive strength of anthracite coal, having reference particularly to the northern anthracite field. This table contains the results of the efforts of that committee, in a condensed form. The committee sent circular letters to the various anthracite operators in the northern field, requesting them to contribute to the efforts of the committee by sending samples in triplicate to be tested. These samples were requested in three sizes, viz.:

Two inches square on the base by 1 inch high, indicated in the table as "1."

Two inches square on the base by 2 inches high, indicated in the table as "2."

Two inches square on the base by 4 inches high, indicated in the table as "4."

These samples were requested to be prepared in each case with the base parallel to the bedding plane of the coal seam, and the height at right angles thereto.

Generous responses to this circular letter were received in the form of some 425 samples for testing, a few of which were defective and not tested. These samples were then divided and sent to the following colleges for testing, the professors named very kindly offering to assist the committee by making the tests:

To Prof. R. C. Carpenter, of the department of experimental engineering, Sibley College, Cornell University, Ithaca, N. Y., 133 samples.

To Prof. Mansfield Merriman, professor of civil engineering, Lehigh University, South Bethlehem, Pa., 177 samples.

To Prof. Louis E. Reber, dean of the school of engineering, Pennsylvania State College, State College, Pa., 113 samples.

After these samples were tested and the results returned to the committee, they were tabulated in a detailed way, forming an immense table, of which this accompanying table is a condensation. The following description of it is given, that the reader may the better understand it:

- 1. The collieries from which the tests were taken are arranged in the column on the left, in order, according to the location of the collieries, beginning at the northerly end of the region near Forest City and ending with the southermost collieries from which tests were received, at Williamstown and Lykens, in the southern coal field.
- 2. The coal beds are arranged at the top of the table in the order of their occurrence in the measures, the highest beds being at the left, and the lowest beds at the right. Where local names for the beds differ from the general names, their local names are inserted in the body of the table.
- 3. The tests are arranged in vertical double columns under the several coal seams, and each test is placed in the column under its respective coal bed and in the horizontal line opposite the colliery from which it was taken.
- 4. Results given in this table are in pounds avoirdupois per square inch of horizontal area.

5. The items given in the columns under the coal double-bed headings are the "First crack," indicating the pressure in pounds per square inch required to produce the first crack in the sample. In other words it is the pressure which would cause the coal of the same quality as the sample to begin squeezing. The items under "Maximum load" in each case indicate the pressure in pounds per square inch at at which the sample crushed. The items under the head of "No. of tests" indicate the number of tests taken from the respective beds in the several collieries, the average of these tests being represented by the figures in the table.

6. The horizontal line headed "General average" contains the average of all the

tests under the respective coal beds as indicated.

The next horizontal line under "General average" indicates the percentage of the maximum load which is represented by the pressure necessary to produce the first crack, or the squeezing pressure. And the second horizontal line under the general average shows the percentage which tests 2 and 4 bear to test 1 in each case.

The grand average, or net result, is contained under a separate heading, and indicates generally the average squeezing and crushing strength as shown by the samples tested. The tests from the several coal fields are tabulated separately, and clearly show the superior strength of the harder coals and the weakness of the softer.

7. From an inspection of this table, the following results appear to apply, approxi-

mately:

That the squeezing strength of a mine pillar whose width is twice its height is about 3,000 pounds to the square inch, and the crushing strength about 6,000 pounds per square inch, or, approximately, twice as much. And in general, other things being equal, the crushing strength of mine pillars would vary inversely as the square root of the thickness of the bed.

The same general rule apparently holds true, also, for the squeezing strength in all cases where the height of the pillar is less than its width. In tall pillars having a height greater than their width, the squeezing strength apparently remains nearly constant, while the crushing strength continues to diminish with height according to the above rule.

WM. GRIFFITH, Chairman.
J. H. FISHER,
MORGAN DAVIS, Jr.

Coal-test Committee, Scranton Engineers' Club.

00	
9	
11.	5
7.07	Ex.
3	line Cy
~	344
5	-
5.	0
3	-
3	7
-	22
20	-
-	111
25	~1
3	S
1	f.
No.J	

k. Baltimore, County. Ross—Arch	Max. load.  Yo. of tests. First crack. Max. load. First crack. We of tests. Pirst crack. Max. load. Max. load.	Top ceal. Bottom coal. 2, 971 5, 6031 21, 475 8, 749 3 4, 423 2, 569 5, 299 3 2, 113 1,500 2, 787 2, 1,410 2,012 31,975	Mills. 6,187 3 3,150 3 2,079 3	Three-foot. 11,500 3,425 1 3,0008,087 11,500 3,425 1 1,500[2,182 11,525 1,975 1 1,250[1,780 1 455 1,872 1	Grassy. 2,564 5,619 3 10 9,891 3 2,564 5,619 3 17,415 3 4,041 5,841 3 53 6,653 3 1,848 2,332 3	6,720 3 3,614 3 3,741 2	3 4,764 4,765 3 4,781 6,963 3 8,802 3,947 3 2,704 5,275 3 8,11,895 2,741 3 1,562 1,600 3
Diamond. Rock. Ball	Max. load. Yo. of fests. Pirst crack. Max. load. Yo. of tests.		2,901 986 1,200		6,410 2,541 5,083	12, 325 5, 176 2 1, 822 6, 316 3 2, 792 8, 485 7, 301 2 1, 167 2, 785 2 1, 628 1, 460 3, 233 3 1, 536 2, 565 2 3, 017	723
Olyphant No. 2. Hillman.	Max. load.    No. of feets.   First crack.   Max. load.   No. of feets.   Yo. of leets.					1,825 6,026 3 2,32 1,131 4,020 3 4,48	2,86
Kidney, b	Height of san First erack.	Vandling b	Coal Brook	Erie 1	Jermyn, D. & II 1	Olyphant	Marvine 2 2 2 1,0141,33

a Test samples 2 inches square by 1 inch high indicated by 1. Test samples 2 inches square by 2 inches high indicated by 2. Test samples 2 inches high indicated by 4.

by 4.

The coal beds are arranged in order as they occur, that is, highest on left and lowest on right. The collieries are arranged in order as located, that is, northern at top an! southern at bottom. All tests in pounds per square inch.

Compressive strength of authracite coal Continued.

NORTHERN COAL FIELD Continue l.

	.stset to .oZ	-: : :		_::::		; ; ;	: : :		:::
Grand average.	Max. load.								
o a	Tirst erack.								
٤ - ١	sison to lov						- ; ; ; -	- : : : -	
Dunmore No. 3.	Max. load.				: : :	_ ; ; ;			
E	First erack.								
0	No. of tests.	111		~ : :			_; ; <u>;</u> _	: : :	
Dunmore No. 2.	Max. load.			33,8214,821					
Da	First erach.			3,821			_!!!!	_ ! ! !	
	stsof to fox		1 : 1	00000		- : : :	-::::-	000	
Dummore Red Ash.	Max. load.			3,228 4,350 2,195				4,500	
Dar	First crack.			312, 343 311, 665 3-1, 650				2,500 2,375 1,500	
بخ	.sisoi lo .oZ	013131							
Clark Ross - Arch.	Max. load.	6, 107		6,274 3,001 1,720	3,500 3,250 3,215	5,462 3,960 3,045		5,700 4,990 2,000	4, 890 4, 125
Cl	First crack.	2,854		4, 113 1,575 805	1,500 1,375 1,875	2,750 2,250 2,250		3,625 11,705	12,137 12,000 11,795
1	No. of tests.	_:::	60 01 30		:::				:
New County.	Max. load.		1,869 4,882 1,662 2,784 1,279 2,832			! ! !	1 2,000 4,000 11,735 1,947 11,537 2,120	3,500 6,875 3,125 4,000 4,315 4,625	2,000 8,970
00	First crack.		1,869				2,000 1,738 1,533	3,50	1,800
	Zo. of tests.	. : :	- : : :	0000	- : : :	_ : : :		1 : :	- : : :
Big Baltinore.	Max. load.			6,381 5,426 1,819			7,000 2,250 645		
Balt	First crack.			3,685 3,900 1,657			5,000 875 520		
	No. of tests.	212121	: .	: : :			- : : :	111	
ين	Max. load.	2221			일일정	,500,			,166
Rock	First crack.	2,2,319 1,2rd 21,8113,221 21,3461,630		: : :	500 3, 200 250 1, 125 970 1, 625	1,2,875,5,500 1,1,820,4,125 1,3,000,3,941			2,675 4,575 1,132 4,165 930,1,160
	Xo. of tests.	2000	- : : :	-:::		1 - 1 - 2 - 2 - 2	1 1 1	-:::	
Diamond.	Max. load.	2,331,3,260 (1,454,3,011) (1,530,2,578)				32,5005,000 31,5003,500 32,5003,200			
lian l		8 2 2	- : :	111	:::	888	T:::	T : :	- : : :
-	First crack.	200			: : : : : : :	0,-0, 0,-0,	111	: : :	_ : : :
ant	Max. load.				::::	00t. 102 343	: : :	: : :	: : :
Olyphant No. 2. Hillman.		-::::			-::::	Four-foot. 5,8816,426 3 2,336 4,102 3 1,930 2,343 8	: : :	: : :	
	First crack.	: : :	1 1 1	- : : :	- : : :	75,04,-	- : : :	: : :	
1 3	.stsot to .oV.		: : :	: : :	: : :	:::	1 : :	: : :	: : :
Kidney.	Max. load.		: : :		111		:::	- : : :	1 : :
	First crack.	-04	-24	- c3 +	-24	- 27 +	- 24	01 4 <sub>1</sub>	- CJ 4
9[1]	Imas to Malait			Aug			-		
	Collieries.	D. & H., Seranton	Leggetts Creek	Dickson	Саупка	Von Storch	D.,I., & W., Scranton	Bellevne	Holden

<u> </u>	:::	:::	:::	:::	:::1	122 116 113 351		
					: : : {	6,014 2,800 2,800	1000	100. 65.5 45.7
						2,978 1,848 1,848	4.9. 5. 4.9. 5. 4.0. 5.	100. 1.1. 1.1.
mmm	2000			: : :		000	- T. T. T.	:::
2017,041 25×3,803 ,4173,109	5,25 4,06 2,14		: : :			2,62	100	100
	31, 287 5, 253 31, 775 4, 062 31, 800 2, 141					91,7446,147 62,0163,933 62,1082,625	8158	100 115 121
350 350 350 350 350	300 E	- : : :	: : :	: : :	: : : !	8824	888	100 # 86
	(2) (2) (2) (2) (3) (3) (4) (4) (5) (5) (6) (6) (6) (6) (6) (6) (6		- : : :			8,49		
1,887	35,0757,646 21,9875,258 32,4883,577					1,95	38.5	100
<b>*</b>		::::	0000	000	000	8 2 2	000	50.8.00
	3,766 3,620 1,895		6,519 3,519 3,275	5,671 2,368 2,620	3,402	5,330 154,378 6,335 9 4,424,141,957 5,480 2,601 152,220 2,947	198	
	1,262	_ ! ! ! _	2 1,994 2 1,732 2 2,259	2,522 1,587 1,550	16,500 11,125 12,315	6,054,22,2,917 4,157,221,714 2,363,221,775	88 88 88 88 88 88 88 88 88 88 88 88 88	38.5
:::::::::::::::::::::::::::::::::::::::	- : : :	111	200 5	111	7,802 2,115 2,360	222	0.00	88.50
			2,550 2,249		2,0,0,	2,4.0		
			2,017 1,410 1,425		6,500 1,500 1,305	92,951 82,402 81,548	55 55	100
		1 1 1	: : :	: : :	::::	243 85	1000	212
			1 1 1		1 1 1	05,985 53,043 2,824		
		: : :				2,45 2,12 1,81	465	100 787
<u>:</u>	-:::	10 th 24	-	000	0000	2222	000	0100
		4,085 3,544 3,182		6,160 2,946 3,179	6,600 10,892 1 4,395 4,395 1 1,250 3,750 1	6, 566 22 2, 450 5 4, 266 22 2, 126 3 3, 295 20 1, SI 7 2	9000	100 50 50
		3 1,700 3 845		2,562 1,887 1,937	6,600 4,395 1,250	3,550	46 45	100
		- mmm	-:::		1 1 1	991	888	\$ 23.0
		_9 0,00 E. 0 0,00 E.		111		15 00 00 T		
		11. Five-foot. 31,727,6,273 32,1162,356 31,9903,665	_	- N 01 01		1,940	87.5	00 8 8 08 8
	:	9 8 8 E	- ; ; ; ;	123	K00 1	10 4 4	1000	61:18
	<del>- i -</del> i	Ben 7.7.0 95,3		10,01,00	Mills. 907,00 876,50	2 4.02	53 1	
		Old Bennett 33,0177,038 3 33,1276,306 3 33,309[5,39] 3		2, 409 5, 870 1, 285 2, 279 2, 596 3, 242	2,1,1	0.2,877	1 1 1	31 E
	-:-	547			975 845 860	204	888	36.
		31,765 6,569 31,568 2,614 31,157 2,547	- : : :	::::	1 2,875 7,975 11,055 1,845 11,627 1,860	43, 122 6, 504, 10.2, 877 5, 407141, 940.5, 41611.3, 550 41, 6183, 409, 102, 122.4, 144.141, 5512, 807101, 990 41, 557, 2, 365, 72, 025.8, 247.151, 673.2, 611.10.2, 101	47	100 52 51
		20 to 20		: : :	1112	444	:::	:::
		7,920 6,216 3,031			6,635 3,082	3,044	0000	0004
-04 -04	: : :	13,4077,9 22,8476,2 42,1503,0		-04	George. 11,5004,250 23,4906,635 41,2503,082	1 2, 930 7, 009 2 3, 008 6, 321 4 1, 925 3, 044	42 47 63	100 105 66
FOT FOT	-017	-64	- N 4	- 21 79	H 64 44	-24	-01	: : :
		nttonwood and Plymouth					roportion 1: First crack + max. load, i.e., percentage	
	2	 Ep				егад	nax.	test ge
woo	. 1111	nom	lale.		oke	al av	rtion x + n pere	tion 14÷ enta
Greenwood	William " A	Buttonwood and Plymouth	Avondale	Alden	Nantieoke	General average	Proportion 1: First crack+max. load, i. e., percentage	Proportion 2: Tests 2 and 4 + test 1, i. e. percentage

Compressive strength of anthracite coal—Continued. EASTERN MIDDLE FIELD.

1	Xo. of tests.	1 11:	1::	1-01-				:: 22   12   12   12   12   12   12   12
Grand average.	Max. load.			7,417 3,857 3,821		8, 631 3, 499 2, 447		3,814 2,377 1,809
C á	First crack.			4,996 3,343 3,413		3,001 788 1,440		1,124 1,099 988
- 2	.stset to .oX	- 1111						::000
Dunmore No. 3.	Maz, load.		-  -  -  -	_ ! ! ! .				Little Lykens Valley. 9763, 025 764 1, 198 735   911
5	First crack.							75 73 73 73 73 73 73 73 73 73 73 73 73 73
2	.sisai lo .oZ	: : :	1 1	-:::				::: 000
Dunmore No. 2.	Jaz. load.		_ ; ; ;	_::::				Lykens Valley. 725,4,131 956.2,937 246.2,262
A	First crack.							
nore Vsh.	Max. load. Xo. of tests.	Mt. 962 1 000 375 1	6,528 3,600 4,833 2	8,053 3 4,066 3 4,347 3		Mt. 500 1 ,000 1		ein
Dunmore Red Ash.	First erack.	Buck Mt. 000 10, 962 000 5,000 000 3,375	2 5, 488 6, 1 3, 113 3, 2 3, 752 4,	3 5, 992 8, 2 3, 742 4, 3 4, 135 4,		Buck Mt. 14,450 6,500 1 968 2,000 1 1,005 1,842 1		White's Vein.  642 4,013 1,175 2,120 1,231 1,612
1	Xo. of tests.	- 5,0,0,	2 3,3,		i	<del></del>		0) 0) 0)
Clark Ross Arch.	Max. load.	Wharton. 500 10, 525 500 5, 400 000 5, 990	5,200 3,000 3,170	6, 975 3, 700 4, 110		9,500 4,497 3,000		No. 7 White Ash 887   3,571   8897   1,566   1,361   3,127   5
Cl	First crack.	Wharton. Buck Mt. 8,500.10,525,17,00010,462 4,500.5,400.15,000.5,000 4,000.5,990.15,000.3,375	1,750 1,500 3,057	3,000 3,371		Seven foot. 1,552 9,500 114 500 4,497 11 11,370 3,000 11		Whit 897 1, 361
	.sisat to .ox			: : :	1 :	:::		2000
New County.	Max. load.				TEL		D.	No. 9 White Ash. 2.2,0634,509 2 2.1,733,219 2.2,841 1,150 2
	First crack.				LE I		TEL	Wh 2,065 1,756 841
e.i	No. of tests.		: : :		100	1000	Z	6228
ek. Baltimore. County.	Max. load.	Mammoth. 5,000 6,825 2,830 3,547 1,375 1,375		6,825 3,547 1,375	WESTERN MIDDLE FIELD	Mammoth. 3,000 9,892 1 895 4,000 1 11,945 2,500 1	SOUTHERN FIELD.	No. 94 White Ash. 1, 442 3, 638 2 1, 615 2, 152 2 1, 515 2, 152 2
Bal	First crack.	Mam 5,000 2,830 1,375		5,000 2,830 1,375	ERI	Ma 3,000 895 1,946	UL	Whw Wh 1,442 1,515
	No. of tests.	1111		::::	ST		S	
Rock.	Max. load.				W			_
, -	First crack.							
	Zo. of tests.			:::				
Diamond.	Max. load.							
Di	First crack.							
i it	No. of tests.		: : :			: : :		
Olyphant No. 2, ITillman.	Max. load.							
0 =	Pirst crack.							
	Xo. of tests.		1 1 1	::::	1	: : :		
Kidney.	Max. load.							
X	First crack.	-04	m 01 m					
.:10	Height of samp	-24	03 m	-04-		-24		-04-04
	Collieries.	Hazleton Ne. 5	Hazleton No. 1	General average		Packer No. 3.		Williamstown

# COMPRESSIVE STRENGTH OF MATERIALS FOR ROOF SUPPORT.

A series of tests of various kinds of materials for supporting the roof in mine workings was made in the Fritz Engineering Laboratory at Lehigh University. The results are given in the following report:

SOUTH BETHLEHEM, PA., January 26, 1911.

Messrs. WILLIAM GRIFFITH and ELI T. CONNER,

Scranton, Pa.

Gentlemen: I beg leave to state that we have concluded the series of tests on the bearing power of materials used in sustaining the roofs of mines, and beg leave to report as follows.

With the exception of a small quantity of sand, all of the materials which we tested were received from you, there being one carload which you sent us from the anthracite coal-mining district. The detailed descriptions of the various tests follow:

#### TEST NO. 1.

This test consisted of crushing a pillar made of mine rock, the four sides of which were laid vertically and then filled with stone of various sizes packed in by hand so as to make a pillar of loose stones without mortar of any kind. This pillar was 5 feet long, 2 feet 4 inches wide, and 18 inches high. It was laid directly on the bedplate of the testing machine and under three steel beams which were later used in applying the load over the entire top surface of the pillar. The stone used was slate, bony coal, and fire clay. The load on this pillar was applied in increments until a maximum pressure of 489,150 pounds was reached. The following table shows the loading at the different stages of the tests, together with the deflections caused by these loads. You will notice that when the total load was 489,150 pounds (approximately 42,000 pounds per square foot) the maximum compression amounted to 5.3 inches.

TEST NO. 2.

Loads and settlements of a rectangular pillar of mine rock.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 4,950 18,550 33,750 46,350 63,025	0.52 .97 1.40 1.81	Pounds, 78, 625 104, 050 130, 350 233, 200	Inches. 2.21 2.74 3.15 3.75	Pounds. 260, 450 326, 450 396, 940 489, 150	Inches. 3.95 4.32 4.83 5.26

This test consisted in crushing a timber crib made of four layers of round timbers which were about 5 inches in diameter and were laid log-house fashion. Each of two of the layers consisted of two of those round timbers 5 feet 4 inches in length and each of the other two layers consisted of three round timbers 2 feet 8 inches in length. The spaces between these timbers were filled with slate, bony coal, and fire clay, and the crib was then filled with small stones shoveled in; the whole resulting in a timber crib 5 feet 4 inches in length, 2 feet 8 inches wide, and  $23\frac{1}{2}$  inches high. The load was applied in increments as shown by the following table. The maximum load reached 900,000 pounds and the maximum settlement was 7.1 inches.

Loads and settlements of a timber crib filled with mine rock.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 5,250 10,550 20,000 30,000 40,200 60,200 80,400 100,000	1nches.  0.49 .78 1.02 1.21 1.48 1.74 1.95	Pounds. 120,000 140,000 179,800 220,000 310,000 370,000	Inches. 2.13 2.33 2.72 3.09 3.44 3.80 4.17	Pounds, 463,000 506,000 604,000 669,000 728,600 780,000 800,000 900,000	Inches. 4.86 5.23 5.80 6.10 6.38 6.71 6.87 7.08

TEST NO. 3.

This test consisted of crushing a circular pillar 28 inches in diameter and 14½ inches high, made of slate arranged so that the outer surface was fairly smooth, the spaces between the stones and the interior of the pillar being filled with small stones. The load was applied in increments as shown in the following table, the maximum load being 361,000 pounds, with a corresponding settlement of 4½ inches.

Loads and settlements of a circular pillar of mine rock.

Loads	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 4,000 20,000 37,000 51,000 60,200	0.19 .65 .75 1.08	Pounds. 71,200 98,000 127,000 150,000 183,000	Inches. 1.29 1.48 1.72 2.50 2.82	Pounds. 195, 400 238, 500 276, 000 361, 600	Inches. 3. 15 3. 69 4. 05 4. 51

After tests Nos. 1, 2, and 3 the stones were found to be very badly crushed, many having been reduced almost to a powder, especially those immediately under the load.

#### TEST NO. 4.

This test consisted in loading a pile of broken stones and observing the settlement caused by the loading. The stone used was crushed sandstone which would pass through a ring 1½ inches in diameter; it had 40 per cent voids, but under the bearing plate on which the load was applied the voids were filled with small broken stones so as to get a secure bearing. The pile of stone was 25 inches wide, 9½ inches high, 2 feet 10 inches long on the top, and 4 feet 5 inches long on the bottom. The load was applied on a cast-iron bearing plate 20 inches square which rested on the top of the pile of stones. The following table gives the loads and the settlement. The maximum load reached was 581,000 pounds, and the maximum settlement was 4.4 inches:

Loads and settlements of a pile of crushed sandstone.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds.	Inches.	Pounds.	Inches.	Pounds,	Inches.
1,400		44.000	1.73	292,000	3.73
2,450		81.400	2.38	437,000	4.10
21,000		141.700	2.97	581,000	4.36

After the test many of the stones were found reduced practically to a powder. The stones under the bearing plate were greatly disintegrated and the plate was pressed downward into the stones. At the ends the pile moved outward as the load was applied, but on the sides the pile was confined by timbers which prevented lateral movement.

#### TEST NO. 5.

This test consisted in crushing a pile of broken sandstone of various sizes up to pieces as large as a man's head. Small stones were placed under the bearing plate. The stones were confined on the sides but were free on the ends and were not laid in any order. The pile was 25 inches wide and 11½ inches high; its length was 3 feet 8 inches on top and 5 feet at the bottom. The load was applied by a cast-iron bearing plate on the top of the pile, the plate being 20 inches square. The following table gives the loads and settlements. The maximum load was 417,000 pounds and the maximum settlement was 4.6 inches.

Loads and settlements of a pile of broken sandstone.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 6,500 21,000 25,000 31,500 33,000	0.32 .46 .61 .69	Pounds. 50,000 72,500 155,500 164,400	Inches. 1.06 1.54 2.35 2.66	Pounds. 194, 300 266, 000 365, 000 417, 000	Inches. 3.21 3.74 4.31 4.61

#### TEST NO. 6.

This test consisted of applying a load to a pile of river sand by means of a 20 by 20 inch bearing plate. The pile was 8 inches deep, 2 feet 6 inches long on top, and 4 feet 2 inches long on the bottom, had a width of 25 inches, and was confined on the sides but not on the ends. The maximum load reached was 600,000 pounds, and the maximum settlement was 5 inches.

# TEST NO. 7.

This test consisted in crushing a pile of broken sandstone, the pile having 40 per cent voids and being of sizes that would pass through a ring 1½ inches in diameter, mixed with river sand in proportions of ten volumes of the broken stone and four volumes of sand. The pile was 10½ inches in depth, 25 inches wide, 2 feet 5 inches long on top, and 4 feet 6 inches long at the bottom; it was confined on the sides but not on the ends. The load was applied on top of the pile through a 20 by 20 inch bearing plate. The following table shows the loads and settlements. The maximum load was 800,000 pounds and the maximum settlement was 4.7 inches.

Loads and settlements of a pile of broken stone and sand.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 2,550 13,000 27,300 52,300	Inches. 0. 67 1. 27 1. 82	Pounds. 100, 000 180, 000 249, 700 337, 600	Inches. 2. 41 3. 02 3. 39 3. 73	Pounds. 488, 000 640, 000 8001000	Inches. 4.13 4.43 4.69

#### TEST NO. 8.

In this test a cast-iron cylinder was filled with coal culm flushed in with water. A piston was then placed on top of the culm and the whole was allowed to stand on a boiler for two days; the cylinder was then placed in the testing machine and pressure was applied to the piston, which in turn communicated the pressure to the culm. within the cylinder. The inside dimensions of the cylinder were as follows: Diameter,  $6\frac{\pi}{8}$  inches; depth,  $10\frac{\pi}{8}$  inches. The depth of the culm in the cylinder was 10 inches. The pressure was applied to the piston and the culm was compressed until the settlement reached 2.7 inches under a load of 200,000 pounds. This load corresponds to a pressure of 6,150 pounds per square inch or 443 short tons per square foot. The loads and settlements are given in the following table:

Loads and settlements of wet coal culm confined in a cast-iron cylinder.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 100 1,100 2,100 3,100 4,100 5,100 6,100 7,100 8,100 9,100	0.10 .19 .27 .32 .36	Pounds. 10,100 12,100 14,100 16,100 18,100 20,100 25,100 30,100 45,000	Inches. 0. 66 .76 .85 .93 1. 01 1. 07 1. 22 1. 34 1. 45 1. 66	Pounds. 55, 400 65, 000 75, 000 85, 400 95, 000 106, 300 124, 670 150, 000 200, 000	Inches. 1.82 1.94 2.04 2.13 2.21 2.32 2.40 2.44 2.73

#### TEST NO. 9.

This test consisted in applying pressure to the piston of a cast-iron cylinder in the same manner as in test No. 8, but the cylinder was filled with broken dry sandstone instead of coal culm. This broken sandstone had 40 per cent voids, and the pieces would all pass through a ring  $1\frac{3}{4}$  inches in diameter. The cylinder was filled to the top, giving a depth of stone of  $10\frac{7}{16}$  inches. The maximum load applied was 300,000 pounds, which caused a settlement of  $3\frac{1}{4}$  inches, or 9,200 pounds per square inch. As a result of the test, the stone was completely crushed and compressed into the iron cylinder so that it had to be cut out with a chisel. The loads and settlements for this test follow:

Loads and settlements of broken sandstone confined in a cast-iron cylinder.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 100 2,000 4,000 6,000 8,000 10,000 12,000 14,000	0. 46 . 72 1. 10 1. 30 1. 43 1. 56 1. 69	Pounds. 16,000 18,000 20,000 25,000 30,000 35,000 40,000 50,000	Inches. 1. 79 1. 89 1. 94 2. 15 2. 32 2. 42 2. 52 2. 67	Pounds. 75,000 100,000 125,000 150,000 175,000 225,000 275,000 300,000	Inches. 2. 91 3. 07 3. 18 3. 28 3. 35 3. 51 3. 55 3. 56

#### TEST NO. 12.

This test was similar to test No. 8 except that the cylinder filled with the culm was allowed to stand, with the piston removed, for eight days over a boiler. The culm was 9 inches deep in the cylinder, and the pressure was applied to the piston until the settlement reached 3 inches under a load of 300,000 pounds. This load corresponds to a pressure of 9,200 pounds per square inch. Although the culm had been drying for eight days, there was considerable water in it; the water was squeezed out during the test. The loads and settlements for this test follow.

Loads and settlements of damp culm confined in a cast-iron cylinder.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 500 1,000 2,000 5,000 10,000 15,000	Inches.  0.057 .175 .452 .786 1.025	Pounds. 20,000 30,000 40,000 50,000 75,000 100,000	Inches. 1, 216 1, 501 1, 708 1, 871 2, 168 2, 373	Pounds. 150,000 200,000 250,000 300,000	Inches. 2. 631 2. 762 2. 876 2. 999

TEST NO. 13.

This test was exactly similar to test No. 8, except that the cast-iron cylinder was filled with dry Delaware River sand; the sand was placed in the cylinder and settled by shaking until it was flush with the top. The load was then applied to the piston until a maximum pressure of 300,000 pounds, with a corresponding settlement of 3.4 inches, was reached. The table showing loads and settlements follows.

Loads and settlements of dry Delaware River sand confined in a cast-iron cylinder.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 100 500 1,000 2,000 5,000 10,000 15,000	0. 13 . 25 . 41 . 65 . 89 1. 07	Pounds. 20,000 30,000 40,000 50,000 75,000 100,000 125,000	Inches. 1.22 1.46 1.66 1.83 2.15 2.39 2.59	Pounds. 150,000 175,000 200,000 250,000 300,000	Inches. 2.75 2.89 3.01 3.20 3.35

TEST NO. 10.

This test consisted in applying pressure to the piston of the cylinder in the same manner as in test No. 9; the broken sandstone had 40 per cent voids; the pieces would all pass through a ring  $1\frac{3}{4}$  inches in diameter, and all voids were filled with river sand. The cylinder was filled to the top, giving the mixture of stone and sand a depth of  $10\frac{7}{16}$  inches. The maximum load applied was 300,000 pounds, or 9,200 pounds per square inch, which corresponded to a settlement of 2.4 inches. As a result of the test the stone was completely crushed and compacted in the iron cylinder. Loads and settlements for the test follow.

Loads and settlements of a mixture of broken sandstone and river sand confined in a castiron cylinder.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 100 1,000 2,000 4,000 6,000 8,000	0.25 .46 .66 .84 .95	Pounds. 10,000 15,000 20,000 30,000 40,000 50,000	Inches. 1. 01 1. 16 1. 27 1. 43 1. 55 1. 65	Pounds. 75,000 100,000 150,000 200,000 250,000 300,000	Inches. 1. 83 1. 95 2. 12 2. 25 2. 34 2. 42

#### TEST NO. 11.

This test consisted in applying a pressure to the piston of the cylinder in the same manner as in test No. 9; but cinders, formed by burning anthracite coal under boilers, were used in the cylinder instead of culm. The cylinder was filled to the top with the cinders, which had 64 per cent voids. The maximum load applied was 300,000 pounds, or 9,200 pounds per square inch, corresponding to a settlement of 5.3 inches. The loads and settlements for this test follow:

Loads and settlements for anthracite-coal cinders confined in a cast-iron cylinder.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 100 700 1,400 2,400 4,000 6,000	0. 45 . 93 1. 38 1. 89 2. 34	Pounds. 10,000 14,000 20,000 34,100 60,000	Inches. 2. 85 3. 23 3. 55 3. 99 4. 41	Pounds. 100,000 150,000 200,000 250,000 300,000	Inches. 4.74 4.98 5.14 5.25 5.33

#### TEST NO. 14.

Pure sand was flushed into a cylinder. The sand was allowed to dry for a period of 48 hours. The top of the sand was  $1\frac{1}{8}$  inches below the top of the cylinder. The following are the results of the test:

Loads and tests of Delaware River sand confined in a cylinder.

Loads.	Settle- ments.	Loads.	Settle- ments.	Loads.	Settle- ments.
Pounds. 650 2,000 5,000 10,000 20,000 30,000	0.05 .12 a.21 .31 .46	Pounds. 40,000 50,000 75,000 100,000 125,000	Inches. 0.56 .67 .90 1.00 1.25	Pounds. 160,000 175,000 200,000 250,000 300,000	Inches. 1.39 1.51 1.60 1.79 1.93

a Water appeared on surface of sand.

# TEST NO. 15.

A pile of blue coal measures sandstone, in pieces 3 inches to 6 inches square, the pile measuring 20½ inches wide, 3 feet 3 inches long on the top, and 9 inches deep, voids on top filled with a small quantity of broken Potsdam sandstone for bearing. On the sides the 3 feet 3 inches dimension was confined by 6-inch by 8-inch timbers; the base plate of the machine and the I beams confined the material on the top and bottom. On the ends the material was free to move outward, but in the test there was very little movement at the ends. The loads were applied to the top of the pile in increments, and the maximum load reached was 600,000 pounds.

The following table gives the loads and the settlements corresponding thereto:

Table of loads and settlements.

Loads.	Settle- ments.	Loads,	Settle- ments.	Loads.	Settle- ments.
Pounds.	Inches.	Pounds.	Inches.	Pounds.	Inches.
3,100	*******	80,000	0.81	232,000	1.56
6,000		90,000	. 88	305,000	1.57
8,000	0.06	100,000	. 93	321,700	1.67
10,000	.12	110,000	. 95	352,000	1.76
15,000	.18	120,000	1.00	375,000	1.82
20,000	. 255	140,000	1.06	395,000	1.89
25,000	. 325	162,000	1.15	425,000	1.97
30,000	. 375	180, 200	1.25	460,000	2.05
41,000	. 48	201,500	1.30	500,000	2.10
50,000	. 55	286,000	1.38	525,000	2.17
60,000	. 62	240,000	1.43	554,000	2.25
70,000	.73	260,000	1.48	600,000	a 2. 43

a This settlement is equivalent to 27 per cent.

Yours, very truly,

FRANK P. McKibben.

0

# **University of Toronto** Library

DO NOT REMOVE THE

CARD

FROM

THIS

POCKET

Acme Library Card Pocket LOWE-MARTIN CO. LIMITED

143203

Mines, Bureau of Bulletin 25.

u.s.

